NO. OF COPIES RECEIVED	3		TOTIVE	Form C-103 Supersedes Old C-102 and C-103
SANTA FE	+/-	NEW MEXICO OIL CONS	ERVATION COMMISSION	Effective 1-1-65
FILE U.S.G.S.		1	,	5a. Indicate Type of Lease
LAND OFFICE	+		APR 4 1969	State X & Fed. XXXXX
OPERATOR	1,	1	1	5, State Oil & Gas Lease No.
	.1		OIL CON. CON	. Various
	SUNDE	RY NOTICES AND REPORTS ON OPOSALS TO DRILL OR TO DEEPEN OR PLUG B TION FOR PERMIT -" (FORM C-101) FOR SUC	WELLS ACK TO A DIFFEREN RESERVO	
I. OIL GAS WELL WEL		OTHER-		7. Unit Agreement Name
2. Name of Operator				8. Form or Lease Name
Beta Development Co. 3. Address of Operator				Fogelson 2 Com.
125 Petr. 0	Club Pl	laza, Farmington, New Mex	ico 87401	1
4. Location of Well				10. Field and Pool, or Wildcat
UNIT LETTER		1550 FEET FROM THE South	LINE AND 1450 FEET	FROM Dasin Dakota
THE <u>East</u>	LINE, SECTI	10N 2 TOWNSHIP 29 N	RANGE 11 W	we ex
	IIIII	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
		5759*	G.L.	San Juan
16.		Appropriate Box To Indicate N NTENTION TO:	-	r Other Data JENT REPORT OF:
OCCUPANT DEMEDIAL WORK	٦	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	╡	PEJG AND ABANBON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	╡	CHANGE PLANS	CASING TEST AND CEMENT JOB	
	-		OTHER	
OTHER				
17. Describe Proposed or Co	ompleted O	perations (Clearly state all pertinent dete	ails, and give pertinent dates, inc	luding estimated date of starting any proposed
in head, pulle bridge plug or Dresser-Atlas collar locator top of wise 18 3-25-69 Fished for in hole. Pick came loose and 4-1/2" csg aretainer 43 + 4% Gel. Dissame cement or out tbg, circle w/100 sx same up to 900%. 3-26-69 WCC. Processert 3250 brid cement &	ed 204 n wire derric r, sett ine l or line ked up d PCH. 4646-50 56*, pu splaced n top c cement MCC. ressure ' WCC tested	jts 1-1/4" upset J-55 tb line - plug was down to ck sheave, dropped sheave ting tool & bridge plug i 1140". 5 5 hrs, recovered 6139". overshot & jars, WIH w/t Layed down fish & fishi 0" & 3536-40" w/2 SPF. W umped thru retainer 800 of retainer. Pulled 28 s ox. 3 bbls good cement ou t, displaced tbg + 2 bbls c down to 10 8 8 M. P C. until 8 P.M. Pressure d pipe to 1500 3 3500" f	g. Rigged up & ran 6139°, still going i and cut line; dropp n hole. WIH w/2-pro Left collar locato bg, found top of fis ng tools, set C.I. b IH w/drillable cemen 6. Picked tbg up outands tbg. (bottom out Spotted cement de Pumped 9 bbls down CH. WIH w/3-7/8" bis tested csg 3250° for 30 mbn, held CK.	worked stuck donut loose gauge ring to 6650°. Ran hole when pin came out of ed 6139° of 7/16" line with any grab on 2-3/8" tbg. Found r, setting tool & bridge plug h 6752°. Jarred fish 6 times ridge plug 6350°. Perfet retainer on 2-3/8" tbg, set w/50 sx 50-50 Pozmix Class C t of retainer, spotted 150 sx f tbg now 2610°). Circ. own tbg, closed rams, squeezed n back side of tbg, pressure t on 2-3/8" tbg, found top of to 1500% for 30 min, held CK.
18. I hereby certify that the	information	n above is true and complete to the best o	of my knowledge and belief.	
SIGNED & J	ay	11 TITLE	Superintendent	DATE 4-3-69
ADDROVED BY		Cleviel	SUPERVISOR DIST. #3	APR 4 1969
CONDITIONS OF APPROVA	LL, IE'AN'			

3-27-69 Continued to drill cement. Tested pipe to 1500. 3700° for 30 min, held CK. Same procedure 3900, 4100 & 4300° for 30 min, held CK. Drld. cement retainer 4358°, bit fell thru to 4420°. Tested pipe to 1200. for 30 min, held CK. Drld. cement to 4500°, tested pipe to 1200; Apeld CK. Drld. out of cement 4650°, tested to 1500. for 30 min, held CK. PCH. Cleaned pit. WIH w/3-7/8" bit on 2-7/8" tbg. Circ. hole clean on top of bridge plug 6350°. Drld. bridge plug, CC to 6745°.

3-28-69 Pulled 2 jts, rigged up and swabbed 7-1/2 hrs, fluid level 5000°, gas on each swab run. POH. Layed down 2-3/8" tbg, picked up Baker Model "G" packer w/S unloader. IIH, ran 204 jts 1-1/6" upset tbg (total 6648°), packer 8 jts off bottom - set packer

6408 . Removed B.Q.P. Higges up well head, released rig 10:00 P.M. 3-29-69.

4-1-69 Rigged up swab unit, swabbed 7 hrs. Well kicked off but died again. 4-2-69 Swabbed 6 hrs, well kicked off, blowing good. Released xwab unit.