Forta 3 160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires March 3 1, 993

NM 03486A

5 Lease Designation and Ser ai No

31	INC	PY	NOT	CES	AND	REPORT	N NO 2	2113
J	ノハレ	ואי	11 0 11	CES	MINU	KER UK I	O O IA AA I	

Use "APPLICATION FOR PERMIT—" for such proposals

6 If Indian Allonee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

SUBMIT IN	7. If Unit or CA, Agreement Designation	
Type of Well Gas Other	3 Well Name and No	
2 Name of Operator		Fogelson 2 COM # 1
CONOCO INC.	9 API Well No	
3 Address and Telephone No	30-045-08686	
10 DESTA DR. STE. 100W, MIDLAND, TX	10 Field and Pool, or Exploratory Area	
4. Location of Well (Footage Sec., T. R. M. or Survey Descrip	Basin Dakota	
Section 2, T-2	11 County or Parish, State	
1550' FSL	& 1450' FEL	
		San Juan, NM
CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, F	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF A	CTION
Notice of Intent	Abandonment	Change of Plans
Subsequent Repon	Recompletion Plugging Back	New Construction Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
		Note: Reponresuits of multiplecompition on Wdl Completion or Recompletion Report and Log form:

13 Describe Proposed or Completed Operations (Clearly state ail pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It has been proposed to repair the casing in this well using the attached procedure.

14 I hereby certify that the foreyand is true and correct		Kay Maddox		February 5, 1999
Signed At Muller	Title	Regulatory Agent	Date	
(This space for Federal or State office use) /S/ Duane W. Spencer	Title	Team Lead, Petroleum Management	Date	EEG 7 100'
Conditions of approval if any				

BLM(6), NMOCD(1), SHEAR, PONCA, COST ASST, FILE ROOM

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its junsdiction



Folgelson 2 Com #1 Slim Hole to Repair Casing February 3, 1999

Procedure

- 1) Hold safety at muster point, determine prevailing wind direction for that location, review procedure and identify potential hazards, isolate surface facilities, bleed off lines, lock out tag out, spot equipment, rig up, **WORK SAFELY!**
- 2) Pull tubing string and packer (check on packer type, believed to be Halliburton R-4 run in 1996) laying down. Tubing String 2.375", 4.7#, J-55, 154 jts. down to packer (Halliburton R-4), 58 jts. down to 1.78" seating nipple on bottom @ 6612'.
- 3) Rig up wireline and set composite EZ Drill bridge plug at 6440' (top perf @ 6509').
- 4) TIH with 3.75" OD Wooley slim hole pipe, (make up Wooley x 8rd cross over to TRW valve for well control), tag plug, unload well with air if possible,
 - Wooley FJ-60-H Hook Thread Casing Performance Data 3.75" OD, 3.25" ID, 3.125" drift, 9.35 Lb./Ft., wall thickness 0.250", grade J-55, 90,000# tensile, min. parting load 158K lbs., maximum string set depth 8449', torque = 8 ft/LB min., & 15 ft/LB max.
- 5) Cement Wooley slim hole pipe in place to surface as per BJ's procedure, pump displacement plug, shut in, wait on cement.
- 6) TIH with work string and 3.125" bit, drill out composite plug @ 6440', clean out to 6770', blow hole dry and POOH laying down.
- 7) TIH with 2.375 CS Hydril, 4.7#, IJ, tubing (2.625" OD connection) with SN & mule shoe on bottom, land @ 6600' plus or minus one joint.
- 8) Notify operator, swab if necessary and put on plunger lifted production. Watch well closely for first two weeks of production. Notify engineering of difficulties.

Note: For x-overs and handling tools for the 3.75" Wooley flush joint slim hole pipe (if not available in Farmington) you can contact Wooley in Kilgore Texas at (903) 984-3556. It would be preferable to order at same time pipe is requested due to shipping costs. Price quotes by Peggy James, M&S, on 2/3/99.

DRW San Juan West Team

Cc: Central Records, Three Copies to Farmington Project Leads