For (I	Form 9-381a (Feb. 1961)					

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	New Mexico
Lease No.	014468
Unit Ho	rell_

NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE F NOTICE OF INTENTION TO TEST WAT NOTICE OF INTENTION TO RE-DRILL NOTICE OF INTENTION TO SHOOT OF NOTICE OF INTENTION TO ABANDON (INDICA)	PLANS FER SHUT-OFF OR REPAIR WELL R ACIDIZE ALTER CASING	SUBSEQUENT REPORT SUBSEQUENT REPORT SUBSEQUENT REPORT SUBSEQUENT REPORT SUBSEQUENT REPORT SUPPLEMENTARY W	RT OF WATER SHUT-OFF	
		December 2	ı , 1960, 19	
/ell No. 1-J is loca	ated 1637 ft. from	$1 - \begin{cases} \mathbf{N} \\ \mathbf{S} \end{cases} $ line and $\frac{\mathbf{T}}{\mathbf{S}}$	ft. from W line of sec.	
(14 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
Blanco	Son Juan (County or Subdivision)		(State or Territory)	
tate names of and expected deptins	ing points, and all	other important proposes	of proposed casings; indicate mudding jobs, ce i work)	
This well was clean 5593. While clean	ing pairts, and an	and a ke line	r was set from \$628 to a fish was lost. The well	
This well was clean 5593. While cleans not perforated.	med out to 5593' ing out liner as Plug and Abandon late on braiden	and a 4" line ter cementing this well in head.	r was set from \$628 to	
This well was clean 5593. While clean not perforated. It is intended to E. l. Weld steel pl. 2. Install a b.	ned out to 5593' ing out liner as Plug and Abendon late on braiden x 4" permanent	and a 4" line ter cementing this well in head. marker.	r was set from \$628 to a fish was lost. The well the following manner:	
This well was clean 5593. While clean not perforated. It is intended to E. Weld steel pl. Weld steel pl. 2. Install a h. I a h.	ing out to 5593' ing out liner as Plug and Abandon late on braiden x 4" permanent	and a 4" line ter cementing this well in head. marker.	the following manner: RECEIVED DEC 28 1950 cal Survey before operations may be commenced.	
This well was clean 5593. While clean not perforated. It is intended to E. I. Weld steel pl. 2. Install a b. I understand that this plan of we Company El Paso Nata	red out to 5593' ing out liner at Plug and Abandon late on braiden x 4" permanent ork must receive approval	and a 4" line ter comenting this well in head. marker.	the following manner: RECEIVED DEC 28 1950 cal Survey before operations may be commenced Original Signed By: D.H. Oheim	
This well was clean 5593. While clean not perforated. It is intended to E. Weld steel pl. Weld steel pl. 2. Install a h. I a h.	red out to 5593' ing out liner at Plug and Abandon late on braiden x 4" permanent ork must receive approval	and a 4" line ter comenting this well in head. marker. By	the following manner: RECEIVED DEC 28 1960 Criginal Signed By: D.H. Oheim	
This well was clean 5593. While clean not perforated. It is intended to E. I. Weld steel pl. 2. Install a b. I understand that this plan of we Company El Paso Nata	red out to 5593' ing out liner at Plug and Abandon late on braiden x 4" permanent ork must receive approval	and a 4" line ter comenting this well in head. marker. By	the following manner: RECEIVED DEC 28 1960 Coloring To Be to the sell survey before operations may be commended to the sell survey before operations and the sell survey before operations	