Form .-331 (May 1963)

OIL OIL

# UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

SUBMIT IN TRIPLICATE\*

Form approved. Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

#### 1-49-110.-54

					_	
6	JF	INDI	AN, ALLO	TTEE O	R TRIBE	NAM

SUNDRY	NOTICES	AND	REPORTS	ON WELL	_S

**GEOLOGICAL SURVEY** 

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

Dry Hole

Barra,	

9. WELL NO.

8.	T.	A R	Ň	OR	LEA	SE 1	IA N	E-
٠.		_	_		· <u></u>			
		Ŷ.	7					
		•						
7.	·U	NI	T.	AGR	E C M	ENT	NA:	ME

	** 222			 	
2.	NAME	OF OPE	BATOR		

# PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

501 Airport Brive, Fernington, New Mexico

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)
At surface

25 10. FIELD AND POOL, OR WILDCAT

U.S.G. Section 18

back Bebots

11. SEC., T., R., M., OB BLK. AND MIN Section 7 7-29-N. 1-16-W

2316' PSL and 990' PKL

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 5040' RDR, 5033' GL

12. COUNTY OR PARISH | 13. STATE

SUBSEQUENT REPORT OF:

How Mexico

16.

### Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

(Other)

PULL OR ALTER CASING MULTIPLE COMPLETE

ARANDON\* CHANGE PLANS WATER SHUT-OFF

FRACTURE TREATMENT SHOOTING OR ACIDIZING


(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL ALTERING CASING ABANDON MENT\*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vestical depths for all markers and zones pertinent to this work.) •

This well having failed to produce oil in commercial quantities, plug and abendon in the following manner:

- Suct 65 eachs coment from \$36' to surface.
- 3 sachs easest into 7-5/8" 4-1/2" annulus.
- Frost FKA marker and clean up location.



U. S. GEOLOGICAL SURVEY N. N. B

18.	I	hereby	certify that the	foregeins ds	Bye and	correct

EATON, JR. SIGNED taton, Jr.

Ares Incineer TITLE


DATE


(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE







Job separation sheet

Form 9-331 (May 1963)	UNITED STATES DEPARTMENT OF THE IN	SUBMIT IN TRIPLICATE (Other instructions on r		
	GEOLOGICAL SURVI		I-89-1HD-58	
SUN (Do not use this	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
1. GAS	OTHER DEY Hole	<del></del>	7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR	OTHER BET MOSE		8. FARM OR LEASE NAME	
PAN AMERICAN	PETROLEUM CORPURATION		USB Section 18	
3. ADDRESS OF OPERATOR			9. WELL NO.	
501 Airport B	rive, Faminaton, New Mox eport location clearly and in accordance wi	th any State requirements	10. FIELD AND POOL, OR WILDCAT	
See also space 17 belo At surface	2310 <b>' 75L</b>		11. SEC., T., R., M., OR BLK. AND SURVEY OR ARBA	
14. PERMIT NO.	15. ELEVATIONS (Show who	nthou DE DE CD ota )	12. COUNTY OR PARISH 18. STATE	
14. PERMIT NO.	GL 5035*, RD		Sin June How Mexico	
1.0			O.L. D.	
16.	•••	cate Nature of Notice, Report, or		
N.	NOTICE OF INTENTION TO:	-) L	QUENT REPORT OF:	
TEST WATER SHUT-OF	PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING WELL ALTERING CASING	
FRACTURE TREAT SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL	CHANGE PLANS	(Other)		
(Other)		(Note: Report resul Completion or Recon	ts of multiple completion on Well pletion Report and Log form.)	
proposed work. If	well is directionally drilled, give subsurfa	ertinent details, and give pertinent date ce locations and measured and true vert	es, including estimated date of starting any ical depths for all markers and zones perti-	
nent to this work.) *	•			
This well wa	s plugged and abandoned a	s follows Aug. 17, 1967:		
	•			
1. <b>3</b> 90	tted 68 anchs commt from	836' to surface.	. •	
	ped 3 macks coment into 7	-5/8" - 4-1/5" emeino es		
Z. Pun	had 2 mars coment men .		· ·	
3. Ere	ered PMA washer, and class	med up location.		
	/	COTUME		
	6	FITIVED \	DECEIVED !	
	/ <b>K</b>	LULI	RECEIVED	
		A 14h/	AUG 2/3 1967	
	<b>\</b> '	OIL CON. COM.		
	₹0	DIST. 3	U. S. GEOLOGICAL SURVEY	
			U. PARMINE	
Approved Aum	se 10, 1967, by John L. V	lard, Anting District Am	Lines.	
and the second second	* · · · · · · · · · · · · · · · · · · ·			
		•		
18. I hereby certify that	the saighing is true and correct			