

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
well well
2. NAME OF OPERATOR
Tenneco Oil Company
3. ADDRESS OF OPERATOR
Box 3249 Englewood, Co 80155
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1030' FSL 1190' FWL "M"
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

SUBSEQUENT REPORT OF:

(other) sidetracking activities ☒

5. LEASE

SF-080246

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Florance

9. WELL NO.

124E

10. FIELD OR WILDCAT NAME

Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 27 T29N R9W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

5717' gr.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
3/17/81. Jar on fish. No recovery. TOH. TIH open ended. Circ hole and set the following cmt plugs; 5870-90' 70sx Class B, 4410-4310' set 20sx Class-B, 3800-3700 20 sx Class-B, 2900-2530' 80 sx Class-B w/10% sand. WOC.
3/18/81. TIH Tag top of cmt @ 2600'. Drill 30' of wet cmt. WOC 4 hrs TOH. TIH open ended and set plug from 2900-2530' w/80 sx Class-B, 10% sand, and 2% CACL₂. TOH.
3/20/81. Drilled cmt to 2740'. RU Nowsco. Unloaded and blow hole dry. POOH. Pick up 4-3/4" corehead, knuckle jt, 1 jt of 2-7/8" drill pipe. TIH. Cut to 2790'. Survey. POOH Laid down corehead and knuckle jt. TIH. Ream to 2790'. Survey POOH. Pick up corehead, knuckle jt.
3/21/81. TOOH w/sidetracking assembly. TIH w/6 1/4" hole opener. LD hole opener. TIH w/bi Drilling ahead.

Subsurface Safety Valve: Manu. and Type _____

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Carolyn H. [Signature] TITLE Asst. Div. Adm. Mgr. DATE March 26, 1981

(This space for Federal or State office use)

APPROVED FOR RECORD
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

APR 07 1981

NMOCC

FARMINGTON DISTRICT

BY [Signature]

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.