Submit 3 Copies to Appropriate District Office

State of New Mexico

Form C-103 Revised 1-1-89

Energy, Minerals and Natural Resources Department

IL CONSERVATION DIVISION P.O. Box 2088	WELL API NO. 30-045-28789
Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease STATE FEE X
	6. State Oil & Gas Lease No.
S AN() REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO R. USE "APPLICATION FOR PERMIT" FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Trujillo 29-10-21
OTHER	
	8. Well No. 2
, NM 87412-0421	9. Pool name or Wildcat Basin Fruitland Coal
Feet From The South Line and 6	45 Feet From The West Line
29ท 10ผ	NMPM San Juan County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
PLUG AND ABANDON REMEDIAL WORK 92 CHANGE PLANS COMMENCE DRILL	CEMENT JOB X
	J-55, ST&C, Casing set @ 259.84', Float @ 216.88', 3 Centralizers 8 Yield/295 cu ft).
Guide Shoe @ 259.84', Insert @ 239.84', 155.84', 71.84'. 250 sx Class B w/2% CaCl (1.1 Circ 9 bbls cement to surface	Float @ 216.88', 3 Centralizers 8 Yield/295 cu ft).
Guide Shoe @ 259.84', Insert @ 239.84', 155.84', 71.84'. 250 sx Class B w/2% CaCl (1.1 Circ 9 bbls cement to surface Fressure tEst BOP Stack & Flo	Float @ 216.88', 3 Centralizers 8 Yield/295 cu ft). • oat Equipment to 600 psi - Held OK
Guide Shoe @ 259.84', Insert @ 239.84', 155.84', 71.84'. 250 sx Class B w/2% CaCl (1.1 Circ 9 bbls cement to surface	Float @ 216.88', 3 Centralizers 8 Yield/295 cu ft). • oat Equipment to 600 psi - Held OK
Guide Shoe @ 259.84', Insert @ 239.84', 155.84', 71.84'. 250 sx Class B w/2% CaCl (1.1 Circ 9 bbls cement to surface Fressure tEst BOP Stack & Flo	Float @ 216.88', 3 Centralizers 8 Yield/295 cu ft). • oat Equipment to 600 psi - Held OK
Guide Shoe @ 259.84', Insert @ 239.84', 155.84', 71.84'. 250 sx Class B w/2% CaCl (1.1 Circ 9 bbls cement to surface Fressure tEst BOP Stack & Florence Fressure Test Casing to 600 p	Float @ 216.88', 3 Centralizers 8 Yield/295 cu ft). • oat Equipment to 600 psi - Held OK si - Held OK.
Guide Shoe @ 259.84', Insert @ 239.84', 155.84', 71.84'. 250 sx Class B w/2% CaCl (1.1 Circ 9 bbls cement to surface Fressure tEst BOP Stack & Florence Fressure Test Casing to 600 p	Float @ 216.88', 3 Centralizers 8 Yield/295 cu ft). • oat Equipment to 600 psi - Held OK si - Held OK.
	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO R. USE "APPLICATION FOR PERMIT" FOR SUCH PROPOSALS.) OTHER OTHER Feet From The South Line and 6 Township 29N Range 10W Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5481 'GL & 5494 'KB TOPPERATE BOX to Indicate Nature of Notice PLUG AND ABANDON REMEDIAL WORK 92 CHANGE PLANS COMMENCE DRILL CASING TEST AND OTHER: Clearly state all pertinent details, and give pertinent dates, in

CONDITIONS OF APPROVAL, IF ANY: