Form 3160-5 \*(December 1989)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: September 30, 1990

5.<sup>7</sup> Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill, deepen or reentry to a different reservoir.					SF 079010
					6. If Indian, Allottee or Tribe Name
		Use "APP	LICATION FOR PERMIT"	for such proposals	
	-				7. If Unit or CA, Agmt. Design.:
SUBMIT IN TRIPLICATE					Northeast Blanco Unit
1. Type of V		oil well	gas well X	other	8. Well Name and No.:
2. Name of Operator: Devon Energy Corpora				- 6 - 6	N.E.B.U. #11
3. Address o			N. Butler Avenue, Suite 211,	, Farmingfon, NM 87461 S	API Well No.:
4. Location	of Well: (Foot	age, Sec., 1., R., M	., or Survey Description)	1 20N2	30-039-07947
					Field & Pool/Exploratory Area:  Blanco Mesaverde
		1550' FNL, 790	FEL, Section 25, T31	N. R7W	11. County or Parish, State:
		1000 1112,770	1 12, 2001011 20, 101		Rio Arriba, New Mexico
12.	· · · · · · · · · · · · · · · · · · ·	CUECK ADDDODE	DIATE DOV(a) TO INDICAT	TE NATURE OF NOTICE DEPORT	
14.	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF SUBMISSION				
				TYPE OF A	
		Notice of Intent		Abandonment	Change of Plans
			:	Recompletion	New Construction
	X	Subsequent Repor	t	Plugging Back	Non-Routine Fracturing
				Casing Repair	Water Shut-Off
	1	Final Abandonmen	t Notice	Altering Casing	Conversion to Injection
				X Other: Remedial	
					s of multiple completion on Well
				···	mpletion Report and Log form.)
starting a	IBE PROPOSE any proposed w to this work.)*	ork. If well is dire	D OPERATIONS (Clearly st ctionally drilled, give subsurf	tate all pertinent details, and give pertiface locations and measured and true	inent dates, including estimated date of vertical depths for all markers and zones
9/24/2002	Work commenced to stop gas flow from the Bradenhead and complete the Lewis interval in this well. Stop gas flow from Bradenhead.				
9/25/02 - 10/1/02	5-1/2" CIBP set in liner @ 5162'. PT 7" csg to 500 psi. Run CBL from 5150' to SFC and TDT from 5150' to 2800'. Evaluate CBL. Discuss path forward with Jim Lovato. Perforate sqz holes @ 3170'. Estimate injection rate. Did not circulate to SFC. Sqz cement through retainer @ 3110' with 100 (26 bbls) sx 50/50 "B" POZ @ 13#, yd 1.47, w/3% gel, 0.8% Halad 9, 5# Gilsonite, 1/4 P/SX Flocele and 0.2% CFR 3. Left 750 psi on retainer. Shoot sqz holes @ 2880'. Cement through PKR @ 2715' w/ 875 sx (230 bbls) 50/50 B POZ cement @ 13# w/ 3% gel, 0.8% Halad 9, 5# Gilsonite, 1/4 P/SX Flocele, 0.2% CFR 3 w/ RQ 6.35. Yd of 1.47. Circulate 5 bbls cement to SFC. Do retainers and cement. PT csg to 750 psi for 15 minutes. PT good. Complete Lewis.				
10/2/2002	Perforate @ 4536', 4516', 4505', 4498', 4450', 4435', 4412', 4374', 4375', 4376', 4378', 4388', 4250', 4251', 4252', 4253'. RIH w/ 3-1/2" tbg for frac.				
10/4/2002	Frac w/70 Q foam and 200,150 pounds of 20/40 Brady sand. Broke @ 4182'. Broke down w/ 1312 gal 15% HCL. Pumped 42,417 gal of 2% KCL and 1,247,673 SCF N2. Max pressure 4916, avg BH rate = 35 bpm, avg psi = 3638 psi.				
10/4/02- 10/14/02	Mill up CIBP @ 5162' and clean to bottom of well. Flow well back to recover frac fluid. Land 2-3/8" tbg @ 5515'. Well is ready for production. Turn well on to production on 10/14/02.				
14. I hereby	certify that the	foregoing is true a	nd correct.		
Signed:	Churk	Francies	CHIICK FREIFE	Title: COMPANY REPRESI	FNTATIVE Date: 10-22-02

Approved by\_ Title Conditions of approval, if any: Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency or the United

(This space for Federal or State office use)