

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Phillips Petroleum Company

3. Address and Telephone No.

5525 Highway 64, NBU 3004, Farmington, NM 87401 505-599-3454

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit ~~H, 2336' FNL & 806' FEL~~ 790 FSL & 790 FNL
Section 35, T31N, R6W

5. Lease Designation and Serial No.

SF-078999

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

San Juan 31-6 Unit

8. Well Name and No.

SJ 31-6 Unit #217

9. API Well No.

30-039-24671

10. Field and Pool, or exploratory Area

Basin Fruitland Coal

11. County or Parish, State

Rio Arriba, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Set packer & on/off tool
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plans are to try and control where gas and water separation occurs. This should solve several production problems. Details of the procedure are as follows:

1. Set wireline plugs.
2. ND WH & NU BOPs.
3. POOH w/tubing.
4. GIH w/tubing, packer and on/off tool. Set EOT @ bottom perf and packer @ TOL. Release from on/off tool. PU 5' and land tubing.
5. ND BOPs and NU WH.
6. Return well to production.

A flow back tank will be utilized instead of a pit.

14. I hereby certify that the foregoing is true and correct.

Signed

Title

Regulatory Assistant

Date

10-6-97

(This space for Federal or State office use)

Approved by

/s/ Duane W. Spencer

Title

Date

OCT 10 1997

Conditions of approval, if any.

* See Instruction on Reverse Side

NMOCD

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.