UNITED STATES			
DEPARTMENT OF INTERIOR		5. Lease Designation and Serial No.	
BUREAU OF LAND MANAGEMENT		SF-078 892 ⁷⁷⁴	
SUNDRY NOTICES AND REPORTS ON WELLS		6. If Indian, Allottee or Tri	be Name.
(Do not use this form for proposals to drill or to			
deepen or plug back to a different reservoir.		7. If Unit or CA, Agreemen	t Designation.
Use Form 3160-3 for such proposals.)		D.O.	CA AINIT
1. Oil well [] Gas Well [X] Other []		ROSA UNIT	
Gas Well		8. Well Name and No.	UNIT #315
2. Name of Operator Evergreen Operating Corporation		9. API Well No.	DRII - 313
3. Address & Telephone No. (505) 334-2555		30-039-25219	
c/o A. R. Kendrick, Box 516, Aztec, NM 87410			
4. Location of Well (Footage & S.T.R.)		Basin-Fruitland Coal Gas Pool	
2548' FSL 2066' FWL		11. County or Parish, State	
K - 30 - T 31 N - R 4 W		Rio Arriba, New Mexico	
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
[] Notice of Intent [] Abandonment	Enrane []	Change Plans
] Recompletion D		New Construction
[•] Subsequent Report] Plugging Back 🚺	Service Control of the Control of th	Non-Routine Fracturing
] Casing Repair		Water Shut-Off
[] Final Abandonment Notice [] Altering CasingOIL CON. DIV. [] Conversion to Injecti			
L] Other	DIST. 3	Dispose Water
13. Describe Proposed or Completed Oper	nations (Give Pentinan	t Notails and Nates)	
10/23/92: Reached T.D. = 350 (
10,20, 32, 1,000,00 1,2,			į.
10/24/92: Attempted to log, hit bridge. Trip in hole to clean out bridge. Ran logs. Prepare to run casing.			
10/25/92: Ran 5-1/2", 17#, J-55, LTC Casing set @ 3499" KB. Float Collar @ 3471', D.V. Tool @			
[2939', Centralizers @ 3472, 3387', 3321' 3254', 3177', 3099', 3016', 2897'*, 2855'*, 2812'*,			
2729', 2663', 2585', 2510', 2340', 2356', 2272' & 2188'. (* Turbolizing Centralizers across the Ujo			
Alamo formation)			
Cemented 1st Stage w/20 barrels	s mud flush followed	by 25 sx 50/50 P0Z & 2	% gel: yield = 32 CuFt. and
100 sx Class B neat w/0.4% Halad 344: yield = 118 Cu.Ft. Totals 1st Stage 125 sx: yield = 150 Cu.Ft.			
Dropped bomb. Opened D.V. Tool, started circulating. Switched to rig pump — pressure went to 1200 psi. Shut down rig pump and rigged up Halliburton, Tested to 2700 psi — no circulation.			
Shut down rig pump and rigged up	Halliburton, lested	to 2700 psi — no circui	ation.
Remove BOP and set slips. Cut off	casing & released ri	o.	
		.	
Shut down for winter.			
NOTE: This form is submitted in lieu of L		5.	<u> </u>
14. I hereby certify that the foregoing is			$\mathbb{Z} \stackrel{\omega}{\hookrightarrow} $
Signed My Kennyale	Title	Agent	Dete FOR RECORD
L	-		Data
Approved by	Title		Date NOV (13.199)
Conditions of approval, if any:			