

F. Loc. 330/S; 1650/W Elev. 5788 GL Spd. 11-1-82 Comp. 8-28-86 TD 1364 PB 1230
Casing S. 8 5/8 @ 9.5 W 31 1/2 C.S. Int. @ W Sx. Pr. 4 1/2 @ 1361 W 291 C.S. T. 11 1/2 yd
Csg. Perf. 992-1012 Prod. Stim.

T
R
A
N
S

I.P. 5 BO/D MCF/D After 24 Hrs. SICIP PSI After Days GOR Grav. 1st Del.

TOPS	NITD	Well Log	TEST DATA						
Kirtland	C-103	Plot	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland	C-104	Electric Log							
Pictured Cliffs		C-122							
Cliff House	Ditr	Dfo							
Menefee	Datr	Dac							
Point Lookout	Set whipstock 10-10-85 1230'-1320' 4x cmt. holdstock 17x-11-11-85 4x-11-11-85								
Mancos									
Gallup									
Sanostee									
Greenhorn									
Dakota									
Morrison									
Entrada									

40

Oswell Farm Co. SJ S 34 T 30N R 11W UN Oper. Lee M. Crane Lse. Martin No. 4

330/S 1650/W 30-045-

F. Loc. SW SE SW Elev. 5730 Spd. 2-14-47 Comp. 5-22-47 TD 1348 PB 1313 before shot
Casing S. @ W Sx. Int. @ W Sx. Pr. 7 @ 1270 W Sx. T. @
Csg. Perf. 100% STPH glys. 1299-1313, shot collapsed bottom joint, showed 5 1/2" hole gray oil after shot.
I.P. 2 BO/D MCF/D After 24 Hrs. SICIP PSI After Days GOR Grav. 1st Del. 8-8-72

T
R
A
N
S
EPC
PL

1-0130-702-78 TOPS BO/D NITD Well Log TEST DATA

TOPS	NITD	Well Log	Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland	C-103	Plot							
Fruitland	C-104	Electric Log							
Pictured Cliffs	11-6-75	C-122							
Cliff House	Ditr	Dfo							
Menefee	Datr	Dac							
Point Lookout	R-6233 Surface Comingle 1-14-75- downhole in area 1 well bond 330 FS 1570 FW 33 1 Paul B. English 14 23								
Mancos									
Gallup									
Sanostee									
Greenhorn									
Dakota									
Morrison									
Entrada									

Oswell Farm Co. SJ S 34 T 30N R 11W UN Oper. Lee M. Crane Lse. Martin No. 3