

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 79-70

Unit

MAR 11 1959

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

26 Feb., 1959

Well No. 79-1 is located 790 ft. from {N} line and 790 ft. from {E} line of sec. 36  
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Alacati (Field) San Juan (County or Subdivision) New Mexico (State or Territory)


The elevation of the derrick floor above sea level is 5400 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugs of neat cement set by Halliburton as follows: (2-26-59)  
(3-5/8" 54' used surface casing left at 94 feet)  
10 sacks from 0-20 feet, with 1" pipe as marker.  
10 sacks from 100-120 feet  
10 sacks from 1000-1050 feet  
10 sacks from 1105-1155 feet

Location cleared & levelled 2-28-59



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Henry S. Birdseye  
Consulting Geologist  
Address P. O. Box 8294  
Albuquerque N. M.  
By Henry S. Birdseye  
Title Operator