Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAL OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS o not use this form for proposals to drill or to re-enter an

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

Lease Serial No. NMSF080597

abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well ☐ Oil Well ☐ Other		THE POLICE TO A			8. Well Name and No. GARTNER A 2		
2. Name of Operator Contact: BP AMERICA PRODUCTION CO		MARY CORLECTION OF THE PROPERTY OF THE PROPERT			9. API Well No. 30-045-09191-00-S1		
3a. Address P. O. BOX 3092 HOUSTON, TX 77253		3b. Phone No. (include area code) Ph: 281.366.4491 Fx: 281.366.0700			10. Field and Pool, or Exploratory BLANCO		exploratory
4. Location of Well (Footage, Sec., T., R., M., or Survey Description		n)		11. County or Parish, and State			
Sec 28 T30N R8W SWNE 1650FNL 1500FWL 36.78534 N Lat, 107.67670 W Lon					SAN JUAN COUNTY, NM		
12. CHECK APPR	ROPRIATE BOX(ES) TO	O INDICATE N	ATURE OF 1	NOTICE, RI	EPORT, OR	OTHER	. DATA
TYPE OF SUBMISSION	SSION TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize	☐ Acidize ☐ Deepen		□ Product		ume)	☐ Water Shut-Off
	☐ Alter Casing	☐ Fracture Treat ☐		☐ Reclama	Reclamation		☐ Well Integrity
☑ Subsequent Report	☐ Casing Repair	epair		☐ Recomplete		⊠ Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon		□ Temporarily Abandon		Workover Operation	
	☐ Convert to Injection	🗖 Plug B	ack 🔲 Water I		Disposal		
determined that the site is ready for fi Please see attached Pay Add Shale pay add activity comple	and Fracture Stimulating	g Subsequent Ro	port for the N	lenefee and	Lewis		
14. I hereby certify that the foregoing is	Electronic Submission	A PRODUCTION (CO, sent to the	e Farmington	ì		
Name (Printed/Typed) MARY CO	Т	Title AUTHORIZED REPRESENTATIVE					
Signature (Electronic S	Submission)	C	eate 06/27/2	002			
	THIS SPACE FO	OR FEDERAL	OR STATE	OFFICE US	SE		
Approved By ACC			PHEN MASC ROLEUM EN		Date 07	7/12/2002	
Conditions of approval, if any, are attached. Approval of this notice does not we certify that the applicant holds legal or equitable title to those rights in the subjection would entitle the applicant to conduct operations thereon.			Office Farmington				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent					ake to any depa	ertment or a	agency of the United

GARTNER A 2 PAY ADD & FRAC SUBSEQUENT REPORT 06/26/2002

05/28/2002 MIRUSU @ 06.00 hrs. Spot EQPT. NDWH & NU BOP's. Unseat TBG hanger. TOH W/TBG.

05/26/2002 TiH W/CIBP & set @ 5060'. TOH. Load hole w/2% KcL water. Pressure test CSG to 1500#. Test OK. RU & GR log.

06/03/2002 RU & Perf Menefee formation w/3.125 inch diameter, 2 JSPF , 16 shots, 32 holes: 4726', 4742', 4754', 4780', 4794', 4810', 4822', 4868', 4922', 4948', 4984', 5003', 5025', 5036', 5048', 5054'.

Set PKR @ 4684'.

06/04/2002 RU & frac W/82,300# of 16/30 Brady Sand & N2 & 70% Quality foam. Flowback well to tank thru 1/2" choke.

06/05/2002 Flowback well thru 1/4" choke. Upsized to 1/2" choke @ 09.30 hrs & flowed back.

06/10/2002 TIH & attempt to set CIBP. Unable to get past liner top @ 4395'.

06/11/2002 TiH & tag bridge @ 4395'. Worked thru tight spot. To top of CIBP set @ 5060'. TOH.

06/12/2002 RU, TIH & set CIBP @ 4580'. RU & perf Lewis Shale formation w/3.125 inch diameter, 2 JSPF, 11 shots, 22 holes:

4046', 4123', 4199', 4296', 4324', 4378', 4414', 4448', 4488', 4502', 4522'.

06/13/2002 Set PKR @ 3800'. RU & frac w/267,557# 20/40 Brady Sand, N2 & 70% Quality foam. RU & flow back thru 1/4" choke overnight.

06/14/2002 Flow back well thru 1/2" choke.

06/19/2002 TIH & tag fill @ 4465". C/O to CIBP set @ 4580'.

06/21/2002 RU & run tracer log.

06/24/2002 TIH & tag fill @ 4542'. C/O to top of CIBP @ 4580'. DO CIBP. TIH & tag fill @ 4977'. C/O to CIBP set @ 5060'. DO CIBP. Circ hole clean. PU above TOL & SDFN.

06/25/2002 TIH & tag fill @ 5110'. Circ hole clean to PBTD @ 5280'. PU above TOL & Flowback well for 12 hrs. thru ¾" choke. 700 MCFD. TIH & tag fill @ 5270'. Circ hole clean to PBTD.

06/26/2002 TIH & tag fill @ 5270'. C/O to PBTD. TOH. TIH W/2 3/8" production TBG & land @ 5138'. ND BOP & NUWH. Pull TBG plug.

06/27/2002 RDMOSU. Service Release @ 07.00 hrs.