## N X 28

## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## WELL RECORD

Mail to Oil Conservation Commission, Santa Fe, New Mexico, or its proper agent not more than twenty days after completion of well. Follow instructions in the Rules and Regulations of the Commission, Indicate questionable data by following

Loc	AREA 640 CATE WELL	ACRES CORRECTLY		it with (?	). SUBMIT IN T	De Commission, in RIPLICATE, FOR PROPERLY FILL	M C-110 V			•	
		Company or	Operator	•		2. Astes,	A	ddress			
	Les	ise				of 8					
						Se west of the Ea				County.	
_	_				_	nment No					
-				-		······					
						,				s - New Mego	
						ng was comple					
						,	Address	Astec	, New . Me	xieo	
		level at top o				•					
he infor	mation giv	en is to be ke	pt confider					19	•		
No 1 from to				OIL SANDS OR ZONEStoto							
•			to			to					
To. 3, fromtoto				No. 6, from							
-				vation to w	TANT WATE	se in hole.	ı				
					4	fe					
	-				<del>9</del> 00		feet		_	_	
						fe					
	<del></del>		1	C	ASING RECO	RD	<u> </u>				
SIZE	WEIGHT PER FOOT	THREADS PER INCH	MAKE	AMOUNT	KIND OF SHOE	CUT & FILLED FROM	FROM	RFORATED		URPOSE	
16*	50#	8 R.D.	Rep.	200	Texas.					urface.	
13-3/1 10-5/1		8		360 700	•				i	stor string	
8-5/1	32	8		1300	•		-				
5-1	14	8		1568	1	.C.Sand Constituted to	T			ow of gas.	
12} 10* 8* aving	-		·····		Lengt	<b>Allegarton</b>	1	Depth Set	······		
iapters	— Materia					Size			••••••	***************************************	
		]	RECORD EXPLOSIV		DOTING OR CHEMICAL TRE		<del>,                                    </del>		1		
SIZE	SHELL	USED	CHEMICAL	USED	QUANTITY	DATE	DEPTH SHOT OR TREATED		DEPTH CLEANED OUT		
<b>5</b> *	Meta	1 181	tro-gly	•	50 Qts	Apr 15t	h-48	33*	1611'		
sults o	f shooting	or chemical	treatment		No incre	se in gas	flow.		••••••	•••••••••••••••••••••••••••••••••••••••	
							***************************************	******	······································	*****************	
drill-ste	em or othe	r special tests				D SPECIAL Ti		sheet and	i attach her	eto.	
ntarv to	ols were w	sed from		feet to	TOOLS USE	eet, and from		faat	t to	fact	
						eet, and from					
					PRODUCTIO						
		<b>April</b> 20									
_						s of fluid of whi					
						as gasoline per					
				Well w	es compet	ted to S.U. ) days, so	P. Lin	e. but	failed	to	
ı	loyd H.	est.				aba Al. Marr					
	-					# - 1					
-		firm that the	informatio	on given he		OTHER SID		d of the w	ell and all w	ork done on	
bscribe	d and swor	n to before m	e this	16 Jam	na <b>ry</b> 1950		g <sub>Ac</sub> lien	-Mexico	3-	16:50	
y of.,	Januar	•		19.	Na:	ne					
She	Chris	3. am	stro	ugh-	Pos	ition					
		Andrew Section	J.N	otary Public	Re	presenting	is.B.W	Many or	Operator		
7 Comm	اند کا چاہا ission expi	res	واما استاد دريه و	. <i>೬ವಳ¥</i>	Add	iressBo	x 182.	Aztec.	New Max	100.	

Address Box 182. Aztec, New Mexico.

FROM	TO	THICKNESS IN FEET	FORMATION
0	**		TMolbees_
10	10 75	Sarface a	<del></del> -
<b>7</b> 5	120	Shale	45
120		, ,	\ \frac{1}{2}
	235	sand rock	
235	295	shale	60
295	525	shale	230
<b>52</b> 5	620	sand rock	85
610	675	shale	65 A A A A A A A A A A A A A A A A A A A
675	690	send rock	15
690	720	shale	30
<b>72</b> 0	755	seed rook	35
<b>75</b> 5	855	shele	100
855	od c	send rock	
865	890	shele	25
4	<b>t</b>		+
890 03.5	915	send rock	
<b>91</b> 5	990	ahole	75
990	995	bana	5
995	1525	spale	<b>530</b>
525	1545	ecal. suni	1 flow water 20
545	1568	Shale	23
568	1630 -	sand. Piet	ure Cliff. 62
^			<b>3.0</b> €
,	7		
`			
1	ŧ		•
	-		

•

4 • • ·

ī

e Au

.