

Re-comp. 10-26-54 5152

F. Loc. 990/S; 990/W

Elev. 6081 DF

Spd.

Comp. 11-6-50 TD 4621

PB

Casing S. 13 3/4 @ 202 W 220 Sx. Int. @ W Sx. Pr. 7 @ 4424 W 250 Sx. T. @
Csg. Perf. Prod. Stim.

Shot 684 qts. 4450-4621

17,230 MCF/D After 3 Hrs. Sic. P. 1017 PSI After 7 Days GOR Grav. 1st Del. 12-50 SUGC

TOPS		NITD	Well Log	TEST	DATA					
Kirtland		C-102	Plat	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland	2406	C-103	Electric Log							
Pictured Cliffs	2805	C-104	X C-110	4/9/54	875	310	542	438	359	4677
Cliff House	4426			4/15/54	887	2688	670	444	4112	461
Menefee	4616	Remarks: Re-worked 10--54. SOF 4870-5037 w. 10,000 GO 7200# Sand. Test reported to be corrected error correction made in 2-5-54		5/27/54	835	2216	617	418	3221	
Point Lookout	5010									
Mancos										
Tocito										
Dakota										
Morrison										
Entrada										
Per 3276										

Jan. Feb. Mar. Apr. May June July Aug. Sept. Oct. Nov. Dec.
Blanco MV co. San Juan s 23 T 30N R 9W U M Oper. Delhi Lse. Florance No. 1-6

Re-Comp. 10-26-54

F. Loc. 990/S; 990/W

Elev. 6081 DF

Spd. 6-7-65

Comp. 11-6-50 TD 5152

PB. 7422

Casing S. 13 3/8 @ 202 W 220 Sx. Int. 4 1/2 @ 7455 W 660 Sx. Pr. 7 @ 4424 W 250 Sx. T. @

Csg. Perf. Prod. Stim. Shot 684 qts 4450-4621
4447-4813 4813-5111

17,230 MCF/D After 3 Hrs. SICP 1017 PSI After 7 Days GOR Grav. 1st Del. 12-50 SUGC

TOPS		NITD	Well Log	TEST	DATA					
Kirtland		C-102	Plat	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland	2406	C-103	Electric Log	4-9-54	875	310	542	438	359	4677
Pictured Cliffs	2805	C-104	C-110	4-15-54	887	2688	670	444	4112	461
Cliff House	4426			5-27-56	835	2216	617	418	3221	
Menefee	4616	Ditr	Dfa	5-15-57	790	1686	610	395	2696	
Point Lookout	5010	Ditr	Dac							
Mancos		Remarks: Re-work 10-54 SOF 4870-5037 w. 10,000 GO								
Gallup				4/15/55	774	1935	632	387	3371	