

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Ladd Petroleum Corporation		8. FARM OR LEASE NAME Butte
3. ADDRESS OF OPERATOR 3535 E. 30th Suite 224A Farmington, New Mexico 87401		9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10. FIELD AND POOL, OR WILDCAT Basin Dakota
1060 FSL 790 FWL		11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA Sec. 19 T30 w R13w
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, CR, etc.) GI 5548	12. COUNTY OR PARISH San Juan
		13. STATE N. M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other) _____	
(Other) _____		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Plan to P&A well as follows

~~Load hole spot 25sx cement. plug @ 6000'~~

Perforate @5150'

~~50' plug inside & outside 41/2 5105- 5055'~~

Perforate @2895'

~~50' plug inside & outside 2895 -2845'~~

Perforate @ 1390'

50' plug inside & outside 1390 -1340'

Perforate @ 250!

Establish circulation with brandenhead & cement w/85 sx. of cmt. (enough cmt. to circulate)

see attached

NOV 16 1987

OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Field Supt.

DATE _____

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE 11/11/78

~~SECRET~~

***See Instructions on Reverse Side**

NMOCG

BUREAU OF LAND MANAGEMENT
CALLER SERVICE 4104
FARMINGTON, NEW MEXICO 87499

Attachement of Notice of
Intention to Abandon

Re: Permanent Abandonment

Well: 1 Butte

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
2. The Farmington Office, telephone (505) 325-4572, is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. The following modifications to your plugging program are to be made (when applicable):

- 1) Bring bottom plug up to 5872' (50' above Dakota top 5922')
- 2) Perf @ 5100, plug inside and outside 4 1/2" casing 5100-5000' Gallup
- 3) " " 2895, " " " " 2895-2795' Mosaverte
- 4) " " 2450, " " " " 2450 2350 Chisera
- 5) " " 1390, " " " " 1390' 1290' Picured cliffs
- 6) " " 860, " " " " 860'-760' Fruitland
- 7) " " 250, " " " " 250'-0'

Office Hours: 7:45 A.M. to 4:30 P.M.