

Remade card

F. Loc. 1850/S; 1850/W Elev. 6222 DF Spd. 5-20-52 Comp. 10-9-52 TD 5281 PB
Casing 9-5/8 @ 172 W 125 Sx. Int. @ W Sx. Pr. 7 @ 4343 W 300 Sx. T. 2 @ 5149
Csg. Perf. Prod. Stim. Shot 1785 qts 4401-5251

I.P. 1230 MCF/D After 6 Hrs. SICP 1070 PSI After Days GOR Grav. 1st Del. 10-28-52 EPNG

TOPS		NITD	Well Log	TEST DATA						
Kirtland	1637	C-102	Plat	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland	2477	C-103	Electric Log	54	918	124	490	459	128	
Pictured Cliffs	2798	C-104	C-110	55	987	82	505	497	82	
Cliff House	4410				726	38	502	363	50	
Menefee	4588	Ditr 12/1/59 11/1/59 1/2/60	Dfa		847	39	477	424	42	
Point Lookout	5078	Datr 1/11/60	Dac							
Mancos		Remarks 2/1/60 part tubing - 9-3-59								
Gallup										
Dakota				4/4/59	173	57	432	219	65	#5283
Morrison				4/1/59	793	365	485	397	418	#632
Entrada				12/6/59	746	320	528	373	434	#5435
				4/1/60	713	311	410	452	228	
Pcd	3424									

W 320

Blanco MV Co SJ S 23 T 30N R 10W U K Oper. EPNG Jan. Feb. Mar. Apr. May June July Aug. Sept. Oct. Nov. Dec. Riddle "B" No 3