

F. Loc. 1650/N; 890/E Elev. 6299DF Spd. 5/7/52 Comp. 10/2/52 TD 5281 PB
Casing 9-5/8 @ 174 W 125 Sx. Int. @ W Sx. Pr. 7 @ 4460 W 300 Sx. T. 2 @ 5234
Csg. Perf. Prod. Stim.

Shot 1785 qts 4521-5275

I.P. 2630 BAXX MCF/D After Hrs. Sic. P. 1083 PSI After 18 Days GOR Grav. Ist Del. 11/5/52 T R A N S E P

TOPS		NITD	Well Log	TEST DATA						
Kirtland	1742	C-102	Plat	Schd.	PC	Q	PW	PD	D	AIL
Fruitland	2608	C-103	Electric Log							
Pictured Cliffs	2903	C-104	C-110	54	873	170	479	437	179	
Cliff House	4501			55	866	136	499	433	148	
Menefee	4676		Remarks	785	124	507	393	147		
Point Lookout	5152			779	119	514	390	147		
Mancos				774	64	485	387	75		\$3099
Toledo										
Dakota										
Morrison										
Entrada										
Pod	3396									

Blanco MV Co. San Juan s 23 T 30N R 10W U H Oper. EPNG Lse. Riddle No. 2-B

Remade test.

F. Loc. 1650/N; 890/E Elev. 6299 D Spd. 5-7-52 Comp. 10-2-52 TD 5281 PB
Casing 9-5/8 @ 174 W 125 Sx. Int. @ W Sx. Pr. 7 @ 4460 W 300 Sx. T. 2 @ 5234
Csg. Perf. Prod. Stim. Shot 1785 qts 4521-5275

I.P. 2630 BAXX MCF/D After Hrs. SICP 1083 PSI After 18 Days GOR Grav. Ist Del. 11-5-52 T R A N S E P NG

TOPS		NITD	Well Log	TEST DATA						
Kirtland	1742	C-102	Plat	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland	2608	C-103	Electric Log	54	873	170	479	437	179	
Pictured Cliffs	2903	C-104	C-110	55	866	136	499	433	148	
Cliff House	4501			785	124	507	393	147		
Menefee	4676			779	119	514	390	147		
Point Lookout	5152			774	64	485	387	75		#3099
Mancos			Remarks							
Gallup			Installed into well 1-28-60							
Dakota			Put to producing 1-28-60							
Morrison				967	200	487	439	200		#5434
Entrada										
Pod	3396									

Blanco MV Co. SJ s 23 T 30N R 10W U H Oper. EPNG Lse. Riddle "B" No. 2