

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

FORM APPROVED  
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

SF 081299-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL  GAS WELL  OTHER  Water Injection well

2. NAME OF OPERATOR

Clinton Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 2434, Casper, Wyoming 82601

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1980' FSL and 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

5389' G. L.

7. UNIT AGREEMENT NAME

J. J. Lommori "A"

8. FARM OR LEASE NAME

N. E. Hogback Unit

9. WELL NO.

16

10. FIELD AND POOL, OR WILDCAT

Horseshoe Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 13-T30N-R16W

12. COUNTY OR PARISH 13. STATE

San Juan

N. M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL


ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Squeeze 25 sks down tbg. below pkr. @ 3880'.  
Set 20 sk. plug 3880'-3730'.  
Load 5 1/2" csg. & shoot @ 2800'.  
Spot 25 sk. plug 2850'-2750'.  
Spot 50 sk. plug 2320'-2170'.  
Spot 30 sk. plug 670'-570'.  
Spot 20 sk. plug 212'-162'.  
Spot 10 sk. plug 30' - GL.  
Install hole marker.



USGS will be notified when location is cleaned up and ready for final inspection.



18. I hereby certify that the foregoing is true and correct

SIGNED Allen B Barnes

TITLE Production Engineer

DATE October 11, 1974

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: