## **UNITED STATES** DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

DOUGHO OF FRIND MAIN	AGENIENT	/	Expirous marci	01, 1000
SUNDRY NOTICES AND REPO	ORTS ON WELLS	RECEIVED	5. Lease Designation and Serial No.	
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT -" for such proposals 98 DEC 14 PM 1: 3			SF - 080601	
Use "APPLICATION FOR PERMIT " 1	for such proposals	-011 PM 1:3	6. If Indian, Allottee or Tribe Name	
7.	<del>-11 1/2 1/11 98</del>	DEC 14		
<u></u>	. K 1903	70 FARMINGTON, !	Unit or CA, Agreement Designation	
10)113	1 8 1300 mg (	70 FAMILIAN		
1. Type of Well Oil Gas Well Other	- CO COUNTO		8. Well Name and No.	
2. Hame of Operator	Attinuion:		SAN JUAN	# 1
AMOCO PRODUCTION COMPANY	Gall M. Jeffer	son	9. API Well No.	
3. Address and Telephone No.  P.O. BOX 800 DENVER COLORADO 80201 303-830-6157			300450	9506
		10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			PICTURED  11. County or Parish, State	CLIFFS
1770 FNL 1610 FWL Sec. 14	F T 30N R 11W	UNIT F	11. County of 1 diss, state	
			San Juan	New Mexico
CHECK APPROPRIATE BOX(s) TO IN	IDICATE NATURE	OF NOTICE, REP	ORT, OR OTHER DA	λTA
TYPE OF SUBMISSION		TYPE OF ACTION		
	X Abandonment	Г		
Notice of Intant	Recompletion		Change of Plans New Construction	
Subsequent Report	Plugging Back		Non-Routine Fracturing	
	Casing Repair Altering Casing		Water Shut-Off Conversion to Injection	
Final Abandonment Notice	Other		Dispose Water	
		(Note: Report resu	sits of multiple completion on Well Completion	or Recompletion Report and Log for
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclimerkers and zones pertinent to this work.)*	luding estimated date of starting any prop	osed work . If well is directionally drilled, giv	e subsurface locations and measur	red and true vertical depths for all
Recently Amoco Production Company requested to permanently plug and abandon the wellbore per ormade not realizing we had cancelled the P&A proofer the P&A operations. Therefore, we are request	ur previously approve cedures in August of	ed P&A procedures dat 1998. We now realize r	ed March 1997. This re	ennest was
If you have any questions please contact Gail Jeffe	erson at (303) 830-61	157		
A brained vicinity that the Caregoing is true and correct				
V5.0.411 Coll		• •		45.46.45.5
Signed Jeen U. Attender	Title	Sr. Admin. Staff A	SST. Date	12-10-1998
in physical für Fedaral or State offica use)				
/S/ Duane W. Spencer	Tial-			DEC   6   1998
Canations of approvei, if any:	Title _		Date	
			· · · · · · · · · · · · · · · · · · ·	
ের 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department	or agency of the United States any false	ficticious, or fraudulent statements or repre	sentations as to any matter within its jurisdic	tion.

San Juan 1
Original Completion 2/58
TD = 2,450'
Page 2 of 2

- 1. Notify regulatory agencies (BLM, NMOCD, FIMO) 24 hours in advance of plugging activity. Contact BLM and indicate well is allotted (FIMO regulations effective April 1, 1997).
- 2. Check location for anchors. Install if necessary. Test anchors.
- 3. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 4. TOH with 1 1/4" tubing. Run in hole with 1 1/4" tubing work string and CIBP, set CIBP at 2311'. Test casing integrity to 500 psi. Spot cement plug from 2311' to 2211' (28 sacks). TOH to 2099', spot cement plug from 2099' to 1999' (28 sacks). TOH, rig up wireline, TIH, perforate at 1106'. Set retainer and circulate cement to surface (279 sacks). Spot cement plug on top of retainer to 896' (31 sacks). TOH to 161', spot 161' cement plug to surface (46 sacks).
- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Contact FMC and ship surface equipment to yard or other location per instructions.
- 7. Provide workorder to Buddy Shaw for reclamation.
- 8. Rehabilitate location according to BLM or State requirements.

## San Juan 1 (PC)

## F14 T30N-R11W, 1770 FNL, 1610 FWL API 3004509506 SF-080601

## **Proposed PXA Wellbore Schematic**

