

GOVERNOR

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

June 30, 1983

Mr. William C. Russel 227 East 59th Street New York, New York 10022

Re: Lunt #62 A-18-30N-13W

Dear Bill:

It appears that the referenced well has a casing failure. You are hereby directed to repair the well. If the well cannot be repaired, you are to plug and abandon it.

If you have any questions, please contact this office.

Yours truly

Frank T. Chavez

District Supervisor

FTC/ca

cc: Mr. Robert Bayless