UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT -" for such proposals SO 101 - 2 PM 2: 03					5. Lease Designation and Serial No. SF-078138-A 6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation	
Type of Well						
Oil Gas Well Other					8. Well Name and No.	#4
AMOCO PRODUCTION COMPANY Gail M. Jefferson					Storey B LS 9. API Well No.	
3. Address and Telaphone No.					3004509624	
P.O. BOX 800 DENVER, COLORADO 80201 (303) 830-6157					10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Desc	ription)				Blanco Mes	averde
1815' FSL 1180	'FWL Sec.	11 T 30N	R 11W	UNIT L	11. County or Parish, State SAN JUAN	NEW MEXICO
CHECK APPROPE	RIATE BOX(s) TO	INDICATE	NATURE O	NOTICE RE	PORT, OR OTHER DA	
TYPE OF SUBMISSION	III/(IZ BOX(0) IO	1110107112	TO THE OT	TYPE OF ACTION	ONT, ON OTHER DA	
Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Operations (Clearly state	Other Parties				Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water sults of multiple completion on Well Completion of the subsurface locations and measure	
Amoco Production Comp but we'ved deciced to rev that these procedures be If you have any technical	rise the procedures. C processed as soon a	consequently, s possible.	revised proced	dures are attached	for your review and app	oroval. We ask
concerns.	questions piease con	iact Dean III	isiey at (303) o		ECEIVE NOV 1 2 1998 IL COIL DIV DIST. 3	
14. I hereby cartify that the foregoing is true and porrect Signed	Efferson		Title	Sr. Admin. Staff	Asst. Date	10-29-1998
(This space for Federal or State office use)	V//					
Approved by			Title		Date	



Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fraudulent statements or representations as to any matter within its jurisdiction.


Atlantic 'B' LS #6 TD = 5520' PBTD = 5507' Page 2 of 2

- 1. Check anchors. MIRUSU.
- 2. Check and record tubing, casing, and bradenhead pressures.
- 3. Blow down wellhead, kill if necessary.
- 4. Nipple down wellhead, nipple up and pressure test BOP.
- 5. TOH with 2.375" tubing (set at 4659'). TIH with Bit X Scraper to PBTD.
- 6. RU DS Wireline Unit and Packoff.
- 7. Set composite BP @ 4560'. Pressure test csg. to 2000#.
- 8. Log Mesa Verde interval with CBL/GR/CCL to insure zonal isolation across MV. Please fax logs to (303)830-5388. Log through CH to approximately 3700'.
- Perforate the following MF interval 120 deg. phasing using 3 1/8 HSC ported guns (12.5* GM, .34" EHD. 13.13* TTP, Select Fire). Correlate with Lane Wells Radioactivity log dated 3/11/55:

4288, 4291, 4295, 4366, 4369, 4392, 4412, 4425, 4428, 4431, 4457, 4462, 4465, 4527, 4530, 4538, 4541

- *Note Perfs. @ 4412, 28, 31, 57, 62, 65 will require penetration through 2 sheaths of casing and cement.
- 10. Break down and balloff perfs with 15 X's excess; 1.1 SG RCN balls.
- 11. Retrieve balls with WL junk basket.
- 12. Fracture Stimulate MF down casing according to schedule 'A'.
- 13. Flow back immediately. Flow starting w/ 1/4" choke, gradually increasing to 1/2" choke. Record and report flowing and shut-in pressures, choke size, and liquid recoveries.
- 14. DO BP, CO to PBTD
- 15. TIH with 2 3/8" tbg, land at 4600'.
- 16. Return well to production; set plunger criteria.

STOREY B LS 004 1806 Location — 11L— 30N—11W SINGLE MV Orig.Completion — 8/56 Last File Update — 1/89 by DDM



е кетакк

Cement

Cement

undan angl

TIFTAM

2710