



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_  
Lease No. \_\_\_\_\_  
Unit \_\_\_\_\_

RECEIVED  
MAR 10 1961

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 6, 1961  
Colorado  
Well No. #2 is located 2310 ft. from [N] line and 2310 ft. from [E] line of sec. 11  
SW SW NE 11 30N 16W NMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Verde San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5479 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 94 feet 8 5/8" J-55 Casing cemented with 30 sacks  
Drilled 8" hole to 810 feet and set 810 feet 7" casing  
Drilled 6" hole to 2003 feet. Ran 2003 feet 4 1/2" casing  
cemented with 50 sacks  
Top of upper Gallup 1835' to 1875'  
Top of Lower Gallup 1965' to 1975'  
Top of Sanastee 1985' to 1990'  
Plan to perforate from 1840' to 1850' and sand/rac.

RECEIVED  
MAR 14 1961  
OIL COMPANY

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company King Oil Company  
Address 735 Petroleum Club Bldg.  
Denver 2, Colorado

By *Benjamin King*  
Title President