

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT -" for such proposals

5. Lease Designation and Serial No.

SF-078316

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Florance Gas Com J

#16

9. API Well No.

3004509800

10. Field and Pool, or Exploratory Area

Blanco Mesaverde

11. County or Parish, State

SAN JUAN

NEW MEXICO

1. Type of Well
☐ Oil Well
☒ Gas Well
☐ Other

2. Name of Operator

AMOCO PRODUCTION COMPANY

Attention:

Gail M. Jefferson

3. Address and Telephone No.

P.O. BOX 800 DENVER, COLORADO 80201

(303) 830-6157

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1010' FNL

990' FEL

Sec. 6

T

30N

R

9W

UNIT A

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Plug back Dakota

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Amoco Production Company has plugged back the Dakota horizon and returned the Blanco Mesaverde to production per the following:
MIRUSU 9/10/98. NUBOP. Unable to release lockdown nuts. Could not PU tbg. Tubing stuck in pkr. Called BLM (Jim Lovato) 9/10/98 to seek permission to revised P&A procedures to allow us to set a cmt retainer on Gallup and squeeze down instead of setting over Dakota. BLM gave permission to leave tbg stuck in Model D pkr at 7420', cut off as close to pkr as possible and cement off.

Set a cmt retainer at 6432'. Squeezed below retainer with 122 sxs Class B and 12 sxs Class B on top of retainer.

TOH with stinger. TIH with production tbg. Tagged PBD at 6402'. PU and land tbg at 5176'.

RDMOSU 9/16/98.

RECEIVED
OCT 15 1998
OIL CON. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct

Signed

Gail M. Jefferson

Title

Sr. Admin. Staff Asst.

Date

09-28-1998

This space for Federal or State office use

Approved by

Conditions of approval, if any:

Title

Date

OCT 07 1998

15. 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.

ADMINISTRATIVE DISTRICT OFFICE

* See Instructions on Reverse Side