

(SUBMIT IN TRIPLICATE)

Indian Agency Sanajo

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allettee

Lease No. 14-20-603-2021

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of Setting Surface Casing

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 12, 1961

#1 Price

Well No. Bayless is located 330 ft. from N line and 3310 ft. from E line of sec. 8

NE 8

(1/4 Sec. and Sec. No.)

30N

(Twp.)

17W

(Range)

NM PM

(Meridian)

Set on

Basin Dakota

(Field)

San Juan

(County or Subdivision)

New Mexico


(State or Territory)

The elevation of the derrick floor above sea level is 5042 ft. 01

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 40' - 7 5/8" Casing - cemented w/20 % cement



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company R. L. Bayless

Address Box 1541

Farmington, New Mexico

By

Title

R. L. Bayless
Partner

