

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-045-09820
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator ENERGEN RESOURCES CORPORATION		6. State Oil & Gas Lease No.
3. Address of Operator 2198 Bloomfield Highway, Farmington, NM 87401		7. Lease Name or Unit Agreement Name: Bandy
4. Well Location Unit Letter <u>N</u> : <u>1196</u> feet from the <u>South</u> line and <u>1992</u> feet from the <u>West</u> line Section <u>3</u> Township <u>30N</u> Range <u>11W</u> NMPM County <u>San Juan</u>		8. Well No. 1
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 5662 GL		9. Pool name or Wildcat Aztec Pictured Cliffs

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Deepen, Case & Frac <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

10/1/01 MIRU. ND wellhead, NU BOP. TOH laying down 104 jts 1" line pipe.  
10/2/01 PU 4-3/4" bit & 2-7/8" tbg, TIH. Drill new hole from 2230'-2330'.  
10/3/01 Land 2-7/8" tbg @ 2326'. Cmt w/250 sks 50/50 Poz "B"(330 cu ft). Plug down @ 12:50 PM 10/3/01.  
Circ 12 BBLS. cmt to surface. RDMO.  
10/8/01 Log Pictured Cliffs.  
10/9/01 Perforate Pictured Cliffs from 2170'-2220' total 30 holes.  
10/12/01 Frac Pictured Cliffs w/33,903# 20/40 Brady sand & 19,200 gals 70Q Amgel 1020.  
10/15/01 MIRU. ND frac valve, NU BOP. TIH w/1-1/4" tbg, tag @ 2138'. Clean out to PBTD @ 2314'.  
10/16/01 Land 1-1/4" tbg @ 2210'. RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Don Graham TITLE Production Superintendent DATE 11/30/01

Type or print name Don Graham Telephone No. 505-325-6800

(This space for SIGNATURE SIGNED BY CHARLIE T. FERTIN

APPROVED BY \_\_\_\_\_ TITLE DEPUTY OIL & GAS INSPECTOR, NM DATE DEC - 4 / 2001  
Conditions of approval, if any:

K