

(SUBMIT IN TRIPLICATE)

Indian Agency **Navajo Tribal**

	X	

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____
Lease No. **14-25-605-738**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANT	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	JUN 23 1959
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 19, 1959

Navajo Navajo

Well No. **5** is located **1900** ft. from **SW** line and **1900** ft. from **E** line of sec. **5**

NE 1/4 Section 5
(4 Sec. and Sec. No.)

20N
(Twp.)

16W
(Range)

NM 20N
(Meridian)

Navajo Indian Res.
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **5300** ft.

DETAILS OF WORK


(State names of and expected depths to objective (sand); show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

6-11-59 Total Depth 1193'

Run 29 joints 5-1/8", 15.500, J-55 Casing (1186') set at 1193' with 25 sacks regular cement, 25 sacks Rammed, 4% gel., 1/4" Flocels per sack.

Held 1800/30 minutes.

Top of cement by temperature survey at 600'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Products Company**

Address **Post Office Box 1505**
Farmington, New Mexico

ORIGINAL SIGNED BY: **JOSEPH E. KREGER**

By

Title **Petroleum Engineer**

LAUNDRY NOTES AND RECORDS

[illegible]

SECRET

01

SECRET

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.



ORIGINAL SIGNED BY: JESSIE E. WRIGHT
