Form 9-331 (May 1963)		UNITED STA	TES	SUBMIT IN TRIPLICATES		oved. ream No. 42-R1424.	
(May 1905)	DEPARTMENT OF THE INTERIOR (Other instructions on re-				5. LEASE DESIGNATION AND SERIAL NO.		
	GEOLOGICAL SURVEY					14-20-603-4905	
	SUNDRY N	6. IF INDIAN, ALLOT	TEE OR TRIBE NAME				
(Do not us	se this form for pr Use "APP	Yeh Nehe P	ah				
1. OIL	GAS	-			7. UNIT AGREEMENT	NAME	
2. NAME OF OPER	WELL OTHE	8. FARM OR LEASE NAME					
	OC ASSOCIAT	9. WELL NO.					
3. ADDRESS OF OF							
P. 1	0. 8ex 776						
4. LOCATION OF W. See also space At surface	ELL (Report locati 17 below.)	10. FIELD AND POOL, OR WILDCAT NOTESSINGS-GALLUP					
1 0	AA fact fr	on South line	. 660 fer	it from East line	11. SEC., T., R., M., O SURVEY OR AR	R BLK. AND EA	
1,950 fest from South line, 660 fest from East line					Sec.2, TSER: R16W		
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)			12. COUNTY OR PARI	SH 18. STATE	
		7,744	MA GABINA		Sall Preser	110 VV 110	
16.	Check	Appropriate Box To	o Indicate No	ature of Notice, Report, or (Other Data		
NOTICE OF INTENTION TO:					QUENT REPORT OF:		
TEST WATER	SHUT-OFF	PULL OR ALTER CASI	₹G	WATER SHUT-OFF	REPAIRING	WELL	
FRACTURE TRE	EAT	MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING	CASING	
SHOOT OR ACT	td ize	ABANDON*	x	SHOOTING OR ACIDIZING	ABANDON	ENT*	
REPAIR WELL	REPAIR WELL CHANGE PLANS (Other) (NOTE: Report result					n on Well	
(Other)				Completion or Recomp	oletion Report and Log	form.)	
to	cover by 5 1 what pro feet balow	O feet. Eduction casin stub.	_	forations with suff	set above and	1 70 11 70	
50 Put Ere Cle	. in surfac ect marker. en up loca .l pits.					RLL VED 101 28 1967 L CON. COM DIST. 3	