Lili lili

## OIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

September 1, 1965

Mr. J. E. Massey Tenneco Oll Company Box 1714 Durange, Colorado 81302

Re: Tenneco 0il Company
Prichard #2, H-1-30N-9W
3lanco Mesaverde Pool

Dear Mr. Massey:

We were contacted recently by Mr. Nell Tefteller regarding the annual deliverability test of the subject well after remedial action.

The data obtained during the test resulted in an impossible answer to the test calculation. Therefore the well must be retested in an effort to obtain usable data.

The allowable change shall be effective April 28, 1965, provided that the deliverability retest report is received in this office on or before November 1, 1965.

If we can be of assistance, please contact us.

Yours very truly

ARK: ks

A. R. Kendrick Engineer, District #3

cc: OCC, Santa Fe, N.M.
SUG, Bloomfield, N.M.

## DIL COMBERVATILIN DOMMER ICH 1000 NO BRAZOB PORT ACCED, NEC MEX 10

en de la companya del companya de la companya del companya de la c

en de la composition La composition de la La composition de la

 $\mathcal{L}_{i}$  , which is a  $\mathbf{a}\mathbf{e}\mathbf{v}^{i}$  ,  $\mathcal{L}_{i}$  ,  $\mathbf{c}$  ,  $\mathbf{c}$  ,  $\mathbf{c}$  ,  $\mathbf{c}$  ,  $\mathbf{c}$