

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Union Texas Petroleum Company	8. Farm or Lease Name Haynie
3. Address of Operator P.O. Box 2120 Houston, Texas 77252-2120	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> <u>1450</u> FEET FROM THE <u>North</u> LINE AND <u>1850</u> FEET FROM THE <u>East</u> LINE, SECTION <u>4</u> TOWNSHIP <u>30N</u> RANGE <u>11W</u> N.M.P.M.	10. Field and Pool, or Wildcat Aztec PC
15. Elevation (Show whether DF, RT, GR, etc.) 5689' DF	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-21-88

Pulled 2200' 1" tubing. Ran 2-3/8" workstring w/5-1/2" cmt. ret.

11-22-88

Set 5-1/2" retainer @ 1925' & squeezed open hole w/100 sx. CL "B" cmt.
Shot 2 holes @ 820' & squeezed w/30 sxs CL "B" cmt.

11-23-88

Circulated 20 sx. CL "B" cmt. to surface. Cut off wellhead below surface.
Ran 4 jts. 1" pipe and circulated 20 sx. CL "B" cmt. to surface.
Set dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Regulatory Permit Coordinator DATE 12-1-88

APPROVED BY _____ TITLE _____ DATE _____

OIL CON. DIV.
DIST. 8

208