BRUCE KING

GOVERNOR

LARRY KEHOE
SECRETARY

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

March 3, 1982

Mr. Perry Pearce Oil Conservation Division Santa Fe, New Mexico 87501

Re: Plugging contracts

Dear Perry:

Please let contracts to plug the following two wells:

(1) Unknown operator and well E-16-30N-11W

An attempt was made to locate this well last summer and partial payment to the pluggers inadvertantly released them from the responsibilities. Contract will require:

- (a) Remove fill dirt from an area approximately 200' by 200' to locate well bore.
- (b) Clean out well to TD approximately 900'.
- (c) Cement to 50' above Farmington formation.
- (d) Perforate casing 50' below Ojo Alamo and cement inside and outside of pipe for 100' from perfs.
- (e) Set surface plug and marker.
- (2) EPROC Associates Monsanto State H #1 E-2-30N-16W Order #R-6370 Plugging procedure
 - (a) Pressure up on well and establish pumping rate into perfs.
 - (b) Pump down wiper plug and tag W/wire line.
 - (c) If plug is below top perforation pump twenty sacks of cement followed by wiper plug and wire line.
 - (d) Displace plug to 1390' WOC.
 - (e) Perforate casing @350'
 - (f) Circulate cement from 350' to surface inside and outside of pipe.
 - (g) Set marker and clean location.

Mr. Perry Pearce March 3, 1982 Page 2

If you have any questions, please call.

Yours truly,

Frank T. Chavez District Supervisor

FTC/lh