

X		

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa FeLease No. W. 02416

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT..... X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 18, 1961

By Byron
Well No. 1 is located 520 ft. from N line and 2250 ft. from E line of sec. 3
NE; NW; Sec. 3 10N 14W T14N
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5654 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spotted 20 cu. ft. cement plug 5150' to 5090', cut off csg. & free point recovered 3800' 5 1/2" csg. Spotted 25 cu. ft. cement plug 3800' to 3725', Spotted 35 cu. ft. cement plug 1150' to 1000', spotted 5 cu. ft. plug at the surface. Installed dry hole marker. Work performed by Halliburton as per "Cementing Service Ticket" #70665 July 6, 1960.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Albert C. Bruce
Address 308 N. Colorado
Suite B
Midland, Texas

By _____
Title Consulting Engineer

