



**NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT**

**AZTEC DISTRICT OFFICE  
1800 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178 Fax (505)334-6170**

**GARY E. JOHNSON  
GOVERNOR**

**JENNIFER A. SALISBURY  
CABINET SECRETARY**

November 8, 1996

Delores Diaz  
Burlington Resources O&G Co  
PO Box 4289  
Farmington NM 87499

RE: Packer Leakage Tests

Dear Dolores:

Please find enclosed the inconclusive 1996 Packer Leakage Tests on the following wells:

Hale #4	H-34-31N-08W	30-045-10119
<del>San Juan 28-5 Ut #29A</del>	D-18-28N-05W	30-039-22229
San Juan 28-5 Ut #88M	E-15-28N-05W	30-039-23856
Tommy Bolack #1	M-01-30N-12W	30-045-24575
Zachry #18	L-11-28N-10W	30-045-07581

These wells need to be rescheduled and retested in a way that proves zone separation and shuts both zones in for a minimum of three days. Flow the higher pressured zone to the atmosphere until the pressure decreases enough to determine if there is zone separation. Notify this office at least 24 hours before the tests, which must be conducted before December 31, 1996, so that we may provide a witness.

Sincerely,

Ernest Cardona  
Deputy O&G Inspector

EC/sh

Enc. 5

cc: well files