X

NEW MEXICO OIL CONSERVATION COMMISSION



MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission District Office within ten days after the work specified is completed. It should be signed and filed as a report on beginning drilling operations, results of shooting well, results of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

agent of the Commission. S	ee additional instruc	ctions in the l	Rules and Regulation	ns of the Commission.	·
	Indicate	nature of repo	ort by checking belo	w.	•
REPORT ON BEGINNING DRILLING			REPORT ON I		
OPERATIONS REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL			REPORT ON I	PULLING OR OTHER	RWISE
REPORT ON RESULT OF TEST OF CASING SHUT-OFF				EEPENING WELL	
REPORT ON RESULT OF I	PLUGGING OF WEI	T			
	Augus	12, 199	2 Date	Aztec, N.M.	Place
Following is a report on the	work done and the re	sults obtained	under the heading no	ted above at the	
Pubce Developme	et Ins.	Stat	Lease	Well No	in the
- TR-	of Sec	32	, T31N	, R8W	, N. M. P. M.,
The dates of this work were					
Shot with 1625 q Well gauged 949	MCF natural.	iified ni		• from 4950	to 5565.
Tom B	Idrigge	8)	Declarate Pastic	oting vo.	SHECTER
APPROVED: OH. CONSERVA	TION COMMISSION	1	is true and correct		
M Mus]	Name	Name /	erles S.	Jeters
Oil and Gas Insp		Title	Position	ogist	
Alig 13 1952			Representing Dune Dense become Trac.		

Date