

STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSIONDISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSanta Fe
Land Office 078506
Lease No. 12 Sec. 26, 31N-9W
Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 30

19 53

Well No. 2 Hunsaker is located 1190 ft. from N line and 1600 ft. from E line of sec. 26
NW 1/4 NE 1/4 Sec. 26 31 North 9 West N.M.P.M.
 (4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft. To be furnished

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The objective sands are the Cliff House and the Point Lookout, expected at about 4675' and 5075' respectively.

Casing Program: 175' of 10-3/4" O.D. casing cemented to top
 4675' of 7" O.D. casing cemented with 200 sacks

Well will be drilled with rotary tools to top of Cliff House and pay sands will be drilled with rotary using natural gas method to a total depth of about 5325'.

Well will then be shot with approximately 1800 quarts of nitro from 4675 to 5325'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SOUTHERN UNION GAS COMPANY

Address Curt Building

Dallas, Texas

By E. M. Anderson

Title District Geologist

DEPARTMENT OF THE INTERIOR
UNITED STATES
(OFFICE OF THE SECRETARY)

HOTEL LORRAINE

ROBERTSON

LONDON

REF ID: A61411

[illegible]

301 30 YOUNG

1. The first step in the process is to identify the problem. This involves gathering information about the situation and the people involved. It is important to understand the context and the stakes of the situation.

[illegible][illegible]

[Faint, illegible handwritten notes]