

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	2. NAME OF OPERATOR Tenneco Oil Co.	3. ADDRESS OF OPERATOR P. O. Box 234, Farmington, New Mexico 87401	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1810/S 970/W +190' FEB, 1190' FNL
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6676' GR		

5. LEASE DESIGNATION AND SERIAL NO. SF 0783368
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME Barrett
9. WELL NO. 1
10. FIELD AND POOL, OR WILDCAT Basin Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20, T31N, R9W
12. COUNTY OR PARISH San Juan
13. STATE N.M.

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

2-07-72 Spotted 30 sacks cement plug 7750-8010'. Laid down 2-3/8" tubing.

6-26-72 Welded onto 5 1/2" casing. Shot off 5 1/2" casing at 719'. Laid down 5 1/2" casing.

6-30-72 Welded onto 7-5/8" casing. Shot off casing at 700'. Laid down casing.

7-05-72 Went in hole with 2-3/8" tubing to 750'. Spotted 40 sacks cement plug at 5 1/2" and 7-5/8" casing stub. Spotted 20 sacks cement plug at 325' and 10 sacks cement plug at surface.

Erected dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED Original signed by T. A. Dugan

TITLE Agent

DATE 4-3-73

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side