

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Tenneco Oil Company		8. FARM OR LEASE NAME Florance	
3. ADDRESS OF OPERATOR P. O. Box 1714 - Durango, Colorado		9. WELL NO. 52	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1830' FSL, 950' FEL Unit H		10. FIELD AND POOL, OR WILDCAT Blanco Pictured Cliffs	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6127' GR	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 20, T-30-N, R-9-W	
		12. COUNTY OR PARISH San Juan	
		13. STATE New Mexico	


16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input checked="" type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Rig up, spud 3-10-66. Drill with Rotary to 111'. Ran 3 joints 8-5/8" 24# J-55 casing landed at 109'. Cemented with 80 sacks cement. Cement circulated to surface. WOC. Drilled cement and drilled to T.D. 2939' on 3-15-66. Ran Welox GR/Density log. Ran 94 joints 3-1/2" 7.7# J-55 10rd casing set at 2937'. Cemented with 490 sacks cement. WOC. Temperature survey shows top of cement 510'. Installed head, released rig 3-14-66. Now waiting on completion rig.



18. I hereby certify that the foregoing is true and correct

SIGNED Harold C. Nichols TITLE Senior Production Clerk DATE 3-16-66

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

Distribution:

- 5 - USGS
- 1 - Continental
- 1 - File

\*See Instructions on Reverse Side