

OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO 1000 RIO BRAZOS ROAD - AZTEC 87410

June 9, 1972

GOVERNOR BRUCE KING CHAIRMAN

LAND COMMISSIONER
ALEX J. ARMIJO
MEMBER

STATE GEOLOGIST
A. L. PORTER, JR.
SECRETARY – DIRECTOR

Aztec Oil & Gas Company P. O. Drawer 570 Farmington, New Mexico 87401

Attention: Mr. Joe Salmon

Dear Mr. Salmon:

The bradenhead test which was conducted on your Nye #14 well in J-13-30N-11W on May 23, 1972, indicates that the production casing has failed.

Please take immediate remedial action to repair the casing in this well.

Federal Form 9-330, Sundry Report, should be filed with the U. S. G. S. office in Farmington setting out proposed remedial action prior to commencing work.

Yours very truly,

Emery C/ Arnold

Supervisor, District #3

ECA:mc

cc: U. S. G. S., Farmington, New Mexico

Oil Conservation Commission, Santa Fe, New Mexico