UNIT				5
DEPARTMENT	OF	THE	INTERIOR	1

SUBMIT IN TRIPLICATE*
(Other instructions on re-

	Form a	pprove	ed.		
	Budget	Bures	in No.	42-R	1424.
LEASE	DESIGN	ATION	AND S	CRIAL	NO.

Form 9-331 (May 1963)	UNITED STATES	SUBMIT IN TRIPLICATE* (Other instructions on re-	Budget Bureau No. 42-R1424.
(214) 1000)	DEPARTMENT OF THE IN	IERIOR verse side)	5. LEASE DESIGNATION AND SERIAL NO.
	GEOLOGICAL SURVE	Y	SF 078116
	TIMEDY MOTICES AND DEDOE	TC ON WELLS 15	6. IF INDIAN, ALLOTTEE OR TEIBE NAME
5	SUNDRY NOTICES AND REPOR	allow book to a different recognist	
(Do not use	this form for proposals to drill or to deepen or Use "APPLICATION FOR PERMIT—" for	such proposals.)	
1.		-3	7. UNIT AGREEMENT NAME
OIL GA	S COTHER	<u> </u>	32
2. NAME OF OPERAT			8. FARM OR LEASE NAME
ET PASO	Natural Gas Company		Florance
3. ADDRESS OF OPER			9. WELL NO.
70× 990.	Farmington, New Mexico		6
4. LOCATION OF WEI	LL (Report location clearly and in accordance wi	th any State requirements.*	10. FIELD AND POOL, OR WILDCAT
See also space 1: At surface:			Undesignated P. C.
_165016, 1	550'E CHANGE		11. SEC., T., E., M., OR ELK. AND SURVEY OR AREA
	OK . Like.		Sec. 24, T-30-2, R-10-
16405	UK .		N.M.P.M.
14. PERMIT NO.	to. ELEVATIONS (Show whe	ther DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	6300	' GT.	San Juan New Mexico
			VI DL.
16.	Check Appropriate Box 10 Indic	ate Nature of Notice, Report, or C	Timer Data
	NOTICE OF INTENTION TO:	BUBSEQU	ENT REPORT OF:
TEST WATER SE	HUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF X	BEPAIRING WELL
FRACTURE TREAT		FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDI	- 	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)	1 K H S A - B T N T
(Other)		(NOTE: Report results	of multiple completion on Well etion Report and Log form.)
	SED OR COMPLETED OPERATIONS (Clearly state all p	antinout details and give partinent dates	including estimated date of starting any
proposed work nent to this wo	k. If well is directionally drilled, give subsurise	ce locations and measured and true vertice	d depths for mi markets and zones perm-
			·왕물림립 · 왕 동원() · 8
0a 7-5-66	a spudded well with spudder	•	《農學濟學》(第二人作》(2)
on 7-7-66	ran 9 joints 8 5/8", 24#, J	-55 casing (291.27') set	at 301.27' w/200
sacks Cla	ass "A" cement w/1/4 cu. ft.	Strata-Crete "6"/sk., 35	calcium chloride
circulate	ed to surface.		그렇듯 흘러 그는 그 중국에 된다.
0.12.01110		3. CO	그런 뭐 할 뿐 이 살이 되어 있다.
		<u>.</u>	. 실회공활 - 1개 강. 장소
			Series Series
		- Andrews	
		JUL 8 1956	
			11 1988
	·	ACC .	JUL 11 1966 OIL CON. COM.
		111 C 18,00	CON. CON.
		JOL	DIST. 3
•		- DEICAL SURVEY	
		U. S. GEOLOGICAL SURVEY	
		- William	ရှင်းမြော်သို့ တွေ့နှာ နှင့်တို့ပြု
			생활원홍활 구원 기가장이
15. I hereby certify	that the foregoing is true and correct		នឹង÷្មីន សត្ស មក្