

Form 5-321
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. 14-20-0165-8412
2. NAME OF OPERATOR Thomas A. Dwyer	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 231, Farmington, New Mexico, 87701	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' FAL, 400' FAL	8. FARM OR LEASE NAME Shoemaker
14. PERMIT NO.	9. WELL NO. 2
15. ELEVATIONS (Show whether DP, RT, CR, etc.) 440' Gr.	10. FIELD AND POOL, OR WILDCAT Willard
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 14 T. 36 N. R. 10 W.
	12. COUNTY OR PARISH San Juan
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all marked and zones pertinent to this work).*

9/5/66 Moved in Crane Drilling Co. Spudded 9 7/8" hole - unable to drill past 25' - shut down - moved rig off hole.

9/6 to
7/16/66 Wait on cable tool rig

9/17/66 Moved in cable tool rig - drilled hole to 50' - set 2 jts. 8 5/8" O.D. surface csg., cemented w/4 sx.

9/19/66 Moved in Crane Drilling Co. rig.

9/20/66 Drilled 7 7/8" hole to 220' with air.

9/21/66 Hole wet - trying to dry up hole.

9/22/66 Drilling at 220' - drilling with air.

9/23/66 Drilling at 375' - drilling with air.

9/28/66 Drilling w/water at 520'.

9/29/66 Drilled 7 7/8" hole to 570' - ran Crane Electric log - temp. abandoned hole.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

