UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS	5. Lease Designation and Serial No.
	SF-080704
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.	6. If Indian, Allottee or Tribe Name
Use "APPLICATION FOR PERMIT - " for such proposals	
	7. If Unit or CA, Agreement Designation
1. Type of Welt	
Oil Sas Other	8. Well Name and No.
2. Name of Operator Attention:	Storey B LS #8
Amoco Production Company Mike Curry	9. API Well No.
3. Address and Telephone No.	3004511955
P.O. Box 800, Denver, Colorado 80201	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Deacription)	Aztec Fruitland Sand Gas, No.
990 FSI 990 FWI Sec. 11 T 30N R 11W	11. County or Parish, State
990 FSL 990 FWL Sec. 11 T 30N R 11W	San Juan New Mexico
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTI	ICE DEPORT OF OTHER DATA
TYPE OF SUBMISSION TYPE OF A	CHON
Abandonment	Change of Plans
Notice of Intent	New Construction
Plugging Back	Non-Routine Fracturing
Subsequent Report Casing Repair	Water Shut-Off
Final Abandonment Notice Altering Casing Other Bradenhead Rep	Dair Conversion to Injection Dispose Water
	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form. }
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	i of starting any proposed work . If well is directionally dillied, give
Please see attached.	
Please see attached.	
•	5 10
	REC 93 JUL 2 070 FAR A
	A C
	MIN 28 BECE
	S A 3
	AHII: 40
to the second of	SEIVED SLM NW NWGTON, NW
AUge	
	4 1993
AUGZ OIL CO)N ~
· Die	in UlV
4. I hereby certify that the foregoing is true and correct	
Signed Mile June Title Busin	ess Analyst Dete 7-26-93
This space for Federal or State office use)	
· · · · · · · · · · · · · · · · · · ·	AUCEPTED FOR RECORD
Approved by Title	Date
Conditions of approval, if any:	41C 1 & 1993

* See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States any false, ficticious or freeded to the United States and false fiction or freeded to the Uni

representations as to any matter within its jurisdiction.

MIRUSU, (7-01-93), BLWDN & KW w/ 20 bbls KCL wtr. Press tst pkg in WH--WH pkg leaked! NDWH, NDBOP & TIH w/ 1.25" tbg. Opn Bradenhd, no flw. BLWDN & KW w/ 15 bbls KCL. PU bit & scr and TIH w/ BP and SP @ 2000'. TOH to 1985'. Ld hole w/ 36 bbls KCL. TOH to 1830'. PU pkr, TIH w/ pkr and set @ 30'w/ 1830' of tail pipe. Press tst BP set @ 2000' and csg to 750 psi, OK! TOH w/ pkr and 2.375" tbg. Run CBL 1000' to surf and cmt top @ 1400'. NDBOP & tbg hgr. Inst new tbg hgr. Tst to 1500 psi, OK! NUBOP, tst to 1500 psi. OK! TIH to 1900' and spot sd on BP set @ 2000'.

<u>Perf:</u> Perf 2 SPF @ 970'. Run dye tst w/ rate set @ .5 BPM @ 1500 psi. Pmpd .5 bbls. Rls SI press. HU to bradenhd and pmpd .25 bbls. Press up to 150 psi. Could not set rate. TIH to 1012' and spot BAL cmt on pg from 1012' to 750'. TOH. Ld hole w/ 2% KCL. Sqz away 2 bbls of cmt into perfs @ 970' to 2000 psi. SI.

TIH w/ bit, scr, DCs & Tag cmt @ 876' DOC to 1012'. Circ hole cln. Press tst csg to 500 psi, OK! TOH. Run CBL fr 1400' to surf. Cmt top @ 912'. TIH w/ strg. TOH and LD DCs. TIH w/ ret hd to rec BP set @ 2000'. TOH. TIH w/ 2.375" tbg & Tag fill @ 2173'. Bot perf @ 2089'. TOH to 2086'.

RUSU and S&F well. TOH w/ 2.375" tbg and LD tbg. TIH w/ 1.25" tbg and ld @ 2094' NDBOP & NUWH. FFCP 95 psi, FFTP 10 psi, SI Bradenhd 0 psi. RDMOSU (7-12-93).