

COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name Lillywhite Gas Com	
9. Well No. 1	
10. Field and Pool, or Wildcat Blanco Mesaverde	
12. County San Juan	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-
2. Name of Operator AMOCO PRODUCTION COMPANY
3. Address of Operator 501 Airport Drive, Farmington, New Mexico 87401
4. Location of Well UNIT LETTER C , 1111 FEET FROM THE North LINE AND 1850 FEET FROM THE West LINE, SECTION 13 TOWNSHIP 30N RANGE 12W NMPM.
15. Elevation (Show whether DE, RT, GR, etc.) 5589' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The Lillywhite Gas Com Well No. 1 was permanently abandoned July 9, 1972, as follows:

1. Spotted 50 sacks Class "A" cement on perms 4285-95', 4310-30', 4455-65' and squeezed 10 sacks in.
2. Spotted 20 sacks cement 1750-2000'.
3. Spotted 20 sacks cement 380-700'.
4. Spotted 10 sacks cement 100' to surface.
5. Cut off wellhead and erected PXA marker.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. ANDREW CHASE TITLE Area Engineer DATE July 11, 1972

APPROVED BY [Signature] TITLE PETROLEUM ENGINEER DIST. NO. 3 DATE 7/11/72
CONDITIONS OF APPROVAL, IF ANY:

