

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well GAS	5. Lease Number SF-077231		
2. Operator Meridian Oil Inc.	6. If Indian, All.or Tribe Name		
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499	7. Unit Agreement Name		
4. Location of Well 790'N, 1090'E	8. Farm or Lease Name Shaw		
	9. Well No. 1R		
	10. Field, Pool, Wildcat Blanco Mesa Verde		
	11. Sec. T. R. M. or Blk Sec. 13, T-30-N, R- 9-W NMPM		
14. Permit No.	15. Elevations 5894' GR	12. County San Juan	13. State NM

16. Intent to/Subsequent Report of :

17. Describe proposed or completed operations:

It is intended to test the 4 1/2" casing integrity and repair if necessary in the following manner:

Perforate 5010-20' w/4 spf. Lay down 2 3/8" tbg and produce the well up 4 1/2" casing in order to reduce excessive erosional velocities existing through the 2 3/8" tbg.

**RECEIVED**  
MAR 26 1990  
OIL CON. DIV  
DIST. 3

18. Authorized by: [Signature] Regulatory Affairs 45 9-19-89 Date

NOTE: This format is issued in lieu of US BLM Form 3160-5

=====  
(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_  
CONDITION OF APPROVAL, IF ANY:

OPERATOR

**APPROVED**  
SEP 28 1989  
[Signature]  
AREA MANAGER



UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

1989  
MAY 1989

Sundry Notices and Reports on Wells

1. Type of Well GAS	5. Lease Number SF-077231		
2. Operator Meridian Oil Inc.	6. If Indian, All. or Tribe Name		
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499	7. Unit Agreement Name		
4. Location of Well 790'N, 1090'E	8. Farm or Lease Name Shaw		
	9. Well No. 1R		
	10. Field, Pool, Wildcat Blanco Mesa Verde		
	11. Sec. T. R. M. or Blk Sec. 13, T-30-N, R- 9-W NMFM		
14. Permit No.	15. Elevations 5894' GR	12. County San Juan	13. State NM

16. Intent to/Subsequent Report of :

17. Describe proposed or completed operations:

It is intended to test the 4 1/2" casing integrity and repair if necessary in the following manner:

Perforate 5010-20' w/4 spf. Lay down 2 3/8" tbg and produce the well up 4 1/2" casing in order to reduce excessive erosional velocities existing through the 2 3/8" tbg.

**RECEIVED**  
MAR 26 1990  
OIL CON. DIV.  
DIST. 3

18. Authorized by: *[Signature]* 9-19-89  
Regulatory Affairs Date

NOTE: This format is issued in lieu of US BLM Form 3160-5

**APPROVED**  
*[Signature]*  
SEP 28 1989  
DATE  
AREA MANAGER

(This space for Federal or State office use)  
APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_  
CONDITION OF APPROVAL, IF ANY:

OPERATOR