

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	Contractor: A-Plus Well Service, Inc.	5. LEASE DESIGNATION AND SERIAL NO. 14-20-0603-7271 A
2. NAME OF OPERATOR R.A. Crane, Jr.	3107 Broadway Highway P.O. Box 1979 Farmington, NM 87499	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo Tribe
3. ADDRESS OF OPERATOR Farmington, NM 87499		7. UNIT AGREEMENT NAME N/A
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 3304' FSL, 2310' FWL S11, T30N, R18W		8. FARM OR LEASE NAME 1 Isador Molk
		9. WELL NO. #1
		10. FIELD AND POOL, OR WILDCAT Wildcat
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 11-T30N-R18W
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH San Juan
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged and abandoned on 8-23-94.

8-23-94

Rig up A-Plus Well Service cementing equipment. Open up well, no pressure. Establish rate down 4-1/2" casing into Gallup formation 1/2 bpm @ 500#. Plug #1: Mix 32 sxs Class B cement (15.6#) down 4-1/2 casing; locked up at 1100#. Pump 5 sxs cement between 7" x 4-1/2" casing annulus, circulated to surface. WOC. Open up well, cement at surface. Cut wellhead off 5' below surface. Weld on P&A marker. Backfill pit and clean up location.

Steve Mason and Kevin Schneider w/ BLM witnessed operations.

18. I hereby certify that the foregoing is true and correct

SIGNED William J. Crane TITLE President DATE 8-31-94

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE FOR RECORD _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

NMOC

SEP 3 1994
FARMINGTON DISTRICT OFFICE
BY SW