

DUGAN PRODUCTION CORP.

THOMAS A. DUGAN, President

709 BLOOMFIELD Rd.
FARMINGTON, NEW MEXICO
March 22, 1968

TELEPHONE: 315-9184 Office
315-5694 Home

Area Code 505

Thomas A. Dugan
King Kong #5
1830' fs1 430' fw1
Sec. 4, T30N, R17W
Elev. 5071' Gr.

- 3/15/68 Depth 440'. Spudded 3/14/68 - drilled with air to 440'. Shut down.
- 3/16/68 Depth 1076'. Drilled with air to 1076' - got first Dakota sand @1064' - no show; drilled to 1076' - had good odor. 1074.5' to 1076' blowing free oil from hole after blowing hole 30 min.
- 3/17/68 Depth 1076' - layed down drill pipe; had indication of water on drill pipe while laying down. Rig down Crane Drilling Co. Mayhew "1000" and rig up Crane Drilling Co. cable tool rig run bailer to 850' (this was all the sand line on rig). Recovered 100% oil estimated fluid level @ 500'. Rig down cable tool rig, rigged up Mayhew "1000". Ran 33 jts. 4 1/2", 9.5#, 8R, ST&C "B" condition csg. T.E. 1064.49 set @ 1064' G1. cemented with 65 sx. regular neat plus 2% Cacl. Bumped plug with 500 psi., left well shut in with 500 psi. P.O.B. 6:30 P.M., 3/16/68.
- 3/18/68 Picked up 3 7/8" bit - blew water from hole, drilled plug and guide shoe. Drilled 2' new hole to 1078' T.D. blowing fair stream of oil from hole. Layed down drill pipe; ran 34 jts. plus 8' pup jt. 2 3/8" O.D., 4.7#, 8R, EUE tbg. T.E. 1064.54 set @ 1066' G1. Well complete 3/17/68.