

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> <i>Contractor:</i>		5. LEASE DESIGNATION AND SERIAL NO. 14-20-0603-8492	
2. NAME OF OPERATOR Westgas		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo Tribe	
3. ADDRESS OF OPERATOR Farmington, NM 87499		7. UNIT AGREEMENT NAME N/A	
4. LOCATION OF WELL (Report location clearly and in accordance with... See also space 17 below.) At surface 330' FNL & 1850' FEL Section 14-T30N-R18W		8. FARM OR LEASE NAME Shiprock	
14. PERMIT NO.		9. WELL NO. #10	
15. ELEVATIONS (Show whether on, at, or above...)		10. FIELD AND POOL, OR WILDCAT 14-T30N-R18W	
11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA 14-T30N-R18W		12. COUNTY OR PARISH San Juan	
13. STATE NM			

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well was plugged and abandoned on 8-25-94.

8-24-94

Rig up cementing equipment and pulling unit. Open up well, no pressure. PU on rods and unseat pump. POH and LD 38 rods (950'). POH and LD 32 jts 2-3/8" tubing (1000'). PU and RIH w/ open ended tubing to 1000'. Plug #1: Mix and pumped 44 sxs 15.6# Class B cement from 1000' to 450'. POH and shut in well. WOC overnight.

8-25-94

Open up well, no pressure. Tag top of cement at 435', Pressure test 4-1/2" casing to 500#, held OK. Perforate 2 squeeze holes at 397'. Establish circulation out bradenhead with 5 bbls water. Plug #2: Mix and pumped 87 sxs Class B cement and circulate 1 bbl good cement out bradenhead. Shut in well. WOC. Dig out wellhead. Install P&A marker with cement. Restore location. RD and MOL.

Steve Mason and Kevin Schneider with BLM witnessed operations.

*A-Plus Well Service Inc* BLM Contract 14226910-C4-2005  
18. I hereby certify that the foregoing is true and correct  
SIGNED *William F. Clark* TITLE President DATE 8-31-94

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

FARMINGTON DISTRICT OFFICE

BY *Smm*

WMOO

SEP 1 1994