## UNITED STATES

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

| <del>-</del>  | ices and Reports on Well:  | s  | <u> </u>                                      |                                     |
|---|--|--|---|-------------------------------------|
|   |  | · · · · · · · · · · · · · · · · · · ·  | 5.  | Lease Number                        |
|   |  |  | ٥.  | SF-078125-B                         |
| 1. Type of Well<br>GAS  |  |  | 6.  | If Indian, All. or<br>Tribe Name    |
|   |  |  | 7.  | Unit Agreement Name                 |
| 2. Name of Operator   | •  |  |   |                                     |
| BURLINGTON  |  |  | · <u>· · · · · · · · · · · · · · · · · · </u> |                                     |
| RESOURCES OIL   | & GAS COMPANY  |  | 3 4<br>3<br>3                                 |                                     |
| 3. Address & Phone No. of Opera   | ) VE   | 2 <b>9</b> [3]   | 8.  | Well Name & Number<br>Pierce A #2   |
| PO Box 4289, Farmington, NM   |  | in the second se |   | API Well No.                        |
| 4. Location of Well, Footage, S   | Sec T P M  |  |   | 30-045-21095<br>Field and Pool      |
| 990'FSL, 1120'FWL, Sec.13, T  |  |  | 10.   | Blanco Pictured Cliff               |
|   | , ,  |  | 11.   | County and State<br>San Juan Co, NM |
| 12. CHECK APPROPRIATE BOX TO IN   | DICATE NATURE OF NOTICE,   | REPORT,  | OTHER   | DATA                                |
| Type of Submission  | Type of Act  |  |   |                                     |
| Notice of Intent  |  | _ Change   |   |                                     |
| Y Cubramient Beneat   |  | _ New Cor  |   |                                     |
| _X_ Subsequent Report   | Plugging Back<br>Casing Repair   | <del></del>  |   | Fracturing                          |
|   |  | water:   | shut of                                       | - <del>†</del>                      |
| Final Abandonment   |  |  | Shut of<br>sion to                            |                                     |
| Final Abandonment   | Altering Casing<br>_X_ Other -   |  |   |                                     |
|   | Altering CasingX_ Other -  |  |   |                                     |
| 9-14-99 RU. TIH w/bai<br>9-15-99 Flow back wel                              | Altering CasingX_ Other -  | Conver   | back v  | vell.                               |
| 9-14-99 RU. TIH w/bai<br>9-15-99 Flow back wel                              | Altering Casing X Other -  Pleted Operations  Ler. Bail snd @ 3059-308 1. Bail snd @ 3069-3083'  | Conver   | back v  | vell.                               |
| Describe Proposed or Comp<br>9-14-99 RU. TIH w/bai<br>9-15-99 Flow back wel | Altering Casing X Other -  Pleted Operations  Ler. Bail snd @ 3059-308 1. Bail snd @ 3069-3083'  | Conver   | back v  | vell.                               |
| Describe Proposed or Comp<br>9-14-99 RU. TIH w/bai<br>9-15-99 Flow back wel | Altering Casing X Other -  Pleted Operations  Ler. Bail snd @ 3059-308 1. Bail snd @ 3069-3083'  | Conver   | back v  | vell.                               |
| Describe Proposed or Comp<br>9-14-99 RU. TIH w/bai<br>9-15-99 Flow back wel | Altering Casing X Other -  Pleted Operations  Ler. Bail snd @ 3059-308 1. Bail snd @ 3069-3083'  | Conver   | back v  | vell.                               |
| 9-14-99 RU. TIH w/bai<br>9-15-99 Flow back wel                              | Altering Casing X Other -  Pleted Operations  Ler. Bail snd @ 3059-308 1. Bail snd @ 3069-3083'  | Conver   | back v  | vell.                               |
| 9-14-99 RU. TIH w/bai<br>9-15-99 Flow back wel                              | Altering Casing X Other -  Pleted Operations  Ler. Bail snd @ 3059-308 1. Bail snd @ 3069-3083'  | Conver   | back v  | vell.                               |
| 9-14-99 RU. TIH w/bai<br>9-15-99 Flow back wel<br>Well turne                | Altering Casing _X_ Other -  pleted Operations  Ller. Bail snd @ 3059-308  L. Bail snd @ 3069-3083'  ed over to production.  | Conver   | back v  | vell.                               |
| 9-14-99 RU. TIH w/bai<br>9-15-99 Flow back wel<br>Well turne                | Altering Casing X Other -  Pleted Operations  Ler. Bail snd @ 3059-308 1. Bail snd @ 3069-3083'  | Conver   | back v  | vell.                               |
| 9-14-99 RU. TIH w/bai<br>9-15-99 Flow back wel<br>Well turne                | Altering Casing _X_ Other -  pleted Operations  Ller. Bail snd @ 3059-308  L. Bail snd @ 3069-3083'  ed over to production.  | Conversion or co | back well. To                                 | vell. DOH w/bailer. RD.             |
| 9-14-99 RU. TIH w/bai<br>9-15-99 Flow back wel<br>Well turne                | Altering Casing  _X_ Other -  pleted Operations  Ller. Bail snd @ 3059-3083'  ed over to production.  Proceeding is true and company to the result of the re | Conversion or co | back well. To                                 | vell. DOH w/bailer. RD.             |