Form 9-331 (May 1963)	DEPAF	UNITED STATES RTMENT OF THE INTER GEOLOGICAL SURVEY	SUBMIT IN TRIPLICATE: (Other instructions on re	Form approvement Budget Bure  5. LEASE DESIGNATION  SF 076386	au No. 42-R1424.
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)  1. OIL GAS [X]				6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
				7. UNIT AGREEMENT N	AMD
WELL WELL L	OTE	CR .		8. FARM OR LEASE NA	ME
El Paso Natural Gas Company				Murphy "	E''
3. ADDRESS OF OPERATOR				9. WELL NO.	
Fig. 990, Farmington, New Mexico 8740].				10. FIELD AND POOL,	OR WILDCAT
4. LOCAT F WELL (Report location clearly and in accordance with any state requirements.  See are space 17 below.)  At surface  990' N, 830' E				Aztec Pictured Clines  11. SEC. T. R. W. OR BEK. AND SURVEY OR LEGA  SEC. 33, T-30-N, F11-W	
		15. ELEVATIONS (Show whether t	DE DE CE Ata	12. COUNTY OR PARIS	H   13. STATE
14. PERMIT NO.		5967' GL	of, RI, UR, CAL,	San Juan	New Mexico
			AL CALL D		
16.		Appropriate Box To Indicate		QUENT REPORT OF:	
R	OTICE OF	INTENTION TO:	SUBSE	- -	
TEST WATER SHUT-OF	F	PULL OR ALTER CASING	WATER SHUT-OFF	A REPAIRING	· ·
PRACTURE TREAT		MULTIPLE COMPLETE	FRACTURE TREATMENT SHOOTING OR ACIDIZING	ABANDONM	
SHOOT OR ACIDIZE		ABANDON"	(Other)		
REPAIR WELL (Other)	<u> </u>	CHANGE PLANS	Mann . Popost rogul	its of muitiple completion appletion Report and Log f	on Well orm.)
nent to this work.) •	Spudde	ed well. Drilled surface losses at the surface of the casing; 125' set at at ated to surface. WOC	ce hole. Ran 3 joint 137'. Cemented with 12 hours, held 600#/3	ts 8 5/8", 24#,	T
	the faren	going is true and correct	U.S. CEOM	bjircts of zies or Thin zirsop or Digit for Life or milleur oalz i no of nollbegrif i dit	glands if armored to the control of