

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Chase Energy, Inc. d/b/a Action Oil, Inc.

3. ADDRESS OF OPERATOR

3301 E. Main, Farmington, New Mexico 87402

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below)
At surface

SE $\frac{1}{4}$, SE $\frac{1}{4}$

264FSL 780FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5032' Ground

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-2027

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo Tribal

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Deb

9. WELL NO.

40

10. FIELD AND POOL, OR WILDCAT

Slickrock Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 36, T30N, R17W

12. COUNTY OR PARISH 13. STATE

San Juan

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☒

(Other) Plug & Abandon ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Called BLM Office as requested on 09/12/90 to advise of intention to plug on 09/13/90. BLM representative Jimmy Morris present on location. Commenced plugging at approx. 2:00 pm. Ran 2-3/8" tubing to bottom (T.D. 800'), set plug #1 from 800' to 400' (30sks). Waited 15 min., mixed 35 sks and set plug #2 from 400' to just below surface. Mixed 5 more sks and came to surface. Cut casing off 4' below surface to set underground marker plate (well is in farmers' field), completed at approximately 4:00 pm.

RECEIVED
NOV 27 1990
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

Herb Benson

TITLE

President

DATE

11/19/90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

[Signature]

*See Instructions on Reverse Side