

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☐ GAS ☒ OTHER ☐		2. NAME OF OPERATOR Tenneco Oil Company		3. ADDRESS OF OPERATOR P. O. Box 3249, Englewood, CO 80155		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1450' 140' FSL, 1025' FEL		5. LEASE DESIGNATION AND SERIAL NO. SF-00004 020004		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
14. PERMIT NO.		15. ELEVATIONS (Show whether SP, ST, etc.) 6042' GL		16. COUNTY OR PARISH San Juan		17. STATE NM		7. UNIT AGREEMENT NAME		8. FARM OR LEASE NAME Florance	
18. FIELD AND HOOL, OR WILDCAT Blanco Fruitland ext. Blanco Mesaverde		19. SEC., T., R., E., OR S.E., AND SURVEY OR AREA Sec. 14, T30N, R9W		20. FIELD AND HOOL, OR WILDCAT Blanco Fruitland ext. Blanco Mesaverde		21. SEC., T., R., E., OR S.E., AND SURVEY OR AREA Sec. 14, T30N, R9W		22. COUNTY OR PARISH San Juan		23. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) recompletion to Fruitland ext.	
(Other) ☐		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11/20/84: MIRUSU. Kill well w/1% KCl wtr. NDWH. NUBOP. Tag fill @4928'.

11/26/84: Kill well. RIH & tag fill @4928. CO to PBD @5197' w/foam. RIH w/7" Model D pkr on WL. Set @2743'. RIH w/tbg to 2500'. Load hole w/1% KCl wtr. Press tst csg in pkr to 3000 psi. Held o.k.

11/27/84: NU old WH & BOP. RIH & jet perf'd 2 HPF w/4" csg gun in following intervals: 2518-26, 2529-34, 2554-60, 2584-90 & 2628-32. PU & RIH w/7" fullbore pkr on tbg. Set @ 2450. Press tst to 1500 psi. Did not hold. Reset pkr @2419'. Press tst to 1500 psi. Held o.k. Acidized w/1160 gals wgt'd 15% HCl & 87-1.1 S.G. balls.

11/28/84: Foam frac'd Fruitland w/52,000 gals 70% qual N₂ foam w/20#'s/1000 gal gelled 1% KCl & 68,000#'s 20/40 sd. AIR = 30 BPM. AIP + 1600 psi. ISIP + 1500 psi. 15 min SIP + 1200 psi. FTCU overnight thru 1/2" tapped bull plug.

11/29/84: Tagged fill @2679'. CO to Model D w/foam. Knock out exp plug. Land long string @4964. PU & RIH w/1-1/4" short string w/perf'd orange peeled shoe, F/N & pmp out plug. Land short string @2615'. NDBOP. NUWH. Pmp out short strg plug & kicked around w/N₂. RDMOSU.

A Well Completion Report (Form 3160-4) is required within 30 days

18. I hereby certify that the foregoing is true and correct

SIGNED <u>[Signature]</u>	TITLE <u>Sr. Regulatory Analyst</u>	DATE <u>DEC 11 1984</u>
(This space for Federal or State office use)		
APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u>DEC 11 1984</u>
CONDITIONS OF APPROVAL, IF ANY:		

FARMINGTON RESOURCE AREA
BY [Signature]

*See Instructions on Reverse Side

NMOCC