

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-0603-639

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NAYAJO

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

KING KONG

9. WELL NO.

13

10. FIELD AND POOL, OR WILDCAT

SALT CREEK

11. SEC., T., R., M., OR BLK. AND
SUBVEY OR AREA

4 - 30N - 17W

12. COUNTY OR PARISH 13. STATE

SAN JUAN NEW MEX.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER DRY HOLE

2. NAME OF OPERATOR
R. A. CRANE, JR.

3. ADDRESS OF OPERATOR
2205 E. MAIN FARMINGTON, NEW MEX. 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

2325 FNL 2470 FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5086' GR.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SPUDDED 6 1/4" HOLE 6/11/75. SET 30' - 5 1/2" casing,
CEMENT WITH 5 SACKS CEMENT. DRILLED 4 3/4" HOLE TO
T.D. 1062'.

INTEND TO P.E.A.:

WILL INSTALL DRY HOLE MARKER AND ABANDON HOLE.

PROPOSED PLUGGING:

CEMENT FROM 1062' to 850' WITH 10 SACKS CEMENT.

CEMENT FROM 603' to 403' WITH 10 SACKS CEMENT.

TOP PLUG AND SET DRY HOLE MARKER.

GALLUP TOP: 453'

DAKOTA TOP: 1033'

T.D. : 1062'

18. I hereby certify that the foregoing is true and correct

SIGNED

Jerome M. Anderson

TITLE

Secretary

DATE

2/10/77

(This space for Federal or State office use)


APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



Chaf